



Shop: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240904070350

Test Time: 2024-09-04 07:03:50

Technician: Werner

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Starlet/--

VIN: JTDJWCA3S00309721

Odometer Reading: 26326

License Plate: LP83CTGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information






Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01514

Version: V4.61

Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine/powertrain	 0
Airbag	 0
Power steering	 0
Lighting and turn signal	 0
Central gateway control module	 1

DTC (1)

Central gateway control module (1 DTC)

DTC	Description	Status
B1150-17	Power source voltage too high	History

Technician Notes

2016518859

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

