

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Accent(RB)/--
VIN: KMHCU51DLEU165933

Odometer Reading: 197776
License Plate: DG75GHGP

Customer Information

Name: We Buy Cars We Buy Cars








Tel: 0870570000

Device information

Scanner: MaxiSys MS906 BT
Version: V13.60

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 4

DTC (6)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0131	Oxygen sensor circuit voltage low (Bank 1 sensor 1)	Pending

AB (Airbag) (1 DTC)

DTC	Description	Status
B2500	Warning lamp failure	History

BCM (Body Control) (4 DTCs)

DTC	Description	Status
B1214	Left rear sensor fault	Active
B1215	Rear center left sensor fault	Active
B1216	Rear center right sensor fault	Active
B1217	Right rear sensor fault	Active

Technician Notes

2016302275

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.