AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20231214132346 Test Time: 2023-12-14 13:23:46

Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Tucson(TL)/--VIN: KMHJ2813MHU513159

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V13.40

Odometer Reading: 159728 License Plate: HD98RGGP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

🔁 System Scanned(10)

System	Status/DTC
ENG (Engine)	O
A/T (Transaxle)	② 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	② 0
AB (Airbag)	② 0
CLU (Cluster Module)	② 0
IMMO (Immobilizer)	O 0
CODE (Transmitter Code Saving)	② 0
EPS (Motor Driven Power Steering)	② 0
BCM (Body Control)	② 0
SJB (Smart Junction Block)	② 0



AUTEL www.autel.com MaxiSys MS906 BT Page 1

Hyundai/ Tucson(TL)/	Test Time	2023-12-14 13:23:46	Report ID:	MAXIA20231214132346
riyuridai/ rucson(rL)/	Test Hille.	2023-12-14 13.23.40	neport ib.	MAXIAZUZJIZIAIJZJAC

Technician Notes

2016203907

Customer name: _	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2