

Shop Name: Dekra MFC Auction House Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250506111825 Test Time: 2025-05-06 11:18:25 Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Veloster/--VIN: KMHTC61DLDU143015

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT Version: V13.86 Odometer Reading: 150842 License Plate: KYB411NW

Tel: 0861033572

Serial Number: VB8GJCC01514 Repair Order Number: --

🔁 System Scanned(9)

ENG (Engine)IABS/ESP (Anti Lock Brake/Electronic Stability Program)1AB (Airbag)0CLU (Cluster Module)1IMMO (Immobilizer)0CODE (Transmitter Code Saving)0A/C (Air Conditioner)0EPS (Motor Driven Power Steering)0BCM (Body Control)0	System	Status/DTC
Program)Image: Constraint of the second	ENG (Engine)	3 1
CLU (Cluster Module)Image: CLU (Cluster Module)Image: CLU (Cluster Module)Image: Cluster Module)IMMO (Immobilizer)Image: Oliver Code Saving)Image: Oliver Oliver Oliver Code Saving)Image: Oliver Oliver Oliver Oliver Steering)Image: Oliver Oliver Oliver Code Saving)A/C (Air Conditioner)Image: Oliver Oliver Oliver Steering)Image: Oliver Oliver Oliver Oliver Code Saving)Image: Oliver Ol		3 1
IMMO (Immobilizer)Image: OCODE (Transmitter Code Saving)Image: OA/C (Air Conditioner)Image: OEPS (Motor Driven Power Steering)Image: O	AB (Airbag)	o
CODE (Transmitter Code Saving)Image: OA/C (Air Conditioner)Image: OEPS (Motor Driven Power Steering)Image: O	CLU (Cluster Module)	3 1
A/C (Air Conditioner) Image: Conditioner of the second s	IMMO (Immobilizer)	o
EPS (Motor Driven Power Steering) \bigcirc 0	CODE (Transmitter Code Saving)	o
	A/C (Air Conditioner)	O
BCM (Body Control) 📀 0	EPS (Motor Driven Power Steering)	O
	BCM (Body Control)	O

🔼 DTC (3)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0326	Knock sensor 1 circuit range/Performance (Bank 1)	Pending
ABS/ESP (An	ti Lock Brake/Electronic Stability Program) (1 DTC)	
DTC	Description	Status
C1688	Vehicle safety management (VSM) 2 (MDPS) signal error	History
CLU (Cluster	Module) (1 DTC)	
DTC	Description	Status
B1603	CAN Communication bus off	History

Technician Notes 2016866320



Customer name:	
Technician: _	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.