

Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241230112735
Test Time: 2024-12-30 11:27:35
Technician: Werner

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Picanto (TA)/--
VIN: KNABE511LHT307965

Odometer Reading: 169492
License Plate: FJ90WWGP

Customer Information

Name: Dekra MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.85

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(6)

System	Status/DTC
ENG (Engine)	 1
AB (Airbag)	 2
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0

DTC (3)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0011	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	Pending

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History

Technician Notes

2016674532



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.