



Shop Name: Dekra MFC Auction House

Tel: --

Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD

KEMPTON PARK

Report ID: MAXIA20250624090947

Test Time: 2025-06-24 09:09:47

Technician: Andrick

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Pride(UB)/--

VIN: KNADN412MG6607694

Odometer Reading: 262699

License Plate: DY10TPGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information









Scanner: MaxiSys MS906 BT

Version: V13.87

Serial Number: VB8GJCC01514

Repair Order Number: --

## System Scanned( 8 )

System	Status/DTC
ENG (Engine)	 1
A/T (Transaxle)	 0
ABS/VDC (Anti Lock Brake system/Vehicle Dynamic Control)	 0
AB (Airbag)	 0
EPS (Motor Driven Power Steering)	 1
BCM (Body Control)	 0
CODE (Transmitter Code Saving)	 0
IMMO (Immobilizer)	 0

## DTC ( 2 )

### ENG (Engine) ( 1 DTC )

DTC	Description	Status
P0335	Crankshaft position (CKP) sensor 'A' circuit	History

### EPS (Motor Driven Power Steering) ( 1 DTC )

DTC	Description	Status
C1702	Variant coding error	Active

## Technician Notes

2016922392



Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.