

Chery VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chery/TIGGO series/Tiggo 8 PLUS/--

VIN: LVVDB11B2PD086762

Odometer Reading: 8614

License Plate: K VX883MP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V10.00

Repair Order Number: --



System Scanned(17)

System	Status/DTC
ECM (Engine system)-EMS (engine management system - China VI - 1.5 T)	✓ 0
ABS (Anti-lock Brake System)/ESP (Electronic Stability Program)	✓ 0
SRS (Supplementary Restraint System)-SRS(Supplementary Restraint System)	✓ 0
IC (Instrument Cluster)-ICM (Instrument Panel Cluster)	✓ 0
TPMS (Tire Pressure Monitoring System)-TPMS (Tire Pressure Monitoring System)	✓ 0
BCM (Body control system)	✓ 0
EPS (Electronic Power Steering System)	✓ 0
IMMO (Immobilizer)-IMMO (engine immobilizer)	✗ 2
PEPS (Keyless start system)-PEPS (Passive Entry Passive Start) - generation 3	✗ 2
RADAR (radar system)	ADAS ✓ 0
SAS (Steering Angle System)	✓ 0
AVM (Panorama Control System)-AVM(Panorama Control System)	ADAS ✓ 0
ESCL (Electronic Steering Column Lock)	✓ 0
RRM (Radio Receiver Module)-RRM(Radio Receiver Module)	✓ 0

IHU (Infotainment Head Unit)

✓ 0

CLM (A/C control system)

✓ 0

CGW (Central Gateway)

✓ 0

 DTC (4)**IMMO (Immobilizer)-IMMO (engine immobilizer) (2 DTCs)**

DTC	Description	Status
B152E	Ignition switch start fault	History DTC
B150C	Clutch switch signal error	History DTC

PEPS (Keyless start system)-PEPS (Passive Entry Passive Start) - generation 3 (2 DTCs)

DTC	Description	Status
B152E	Ignition switch start fault	History
B150C	Clutch switch signal error	History

Technician Notes

2016211794

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.