



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250506094130
Test Time: 2025-05-06 09:41:30
Technician: Trevino

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Cerelio/--
VIN: MA3TFC62S00158009

Odometer Reading: 57196
License Plate: JDD456FS

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V4.70

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine/powertrain	 0
ABS/ESP	 6
Airbag	 0
Instrument Panel Cluster (IPC)/meter/M&A	 0
Power steering	 0
BCM	 0
Immobilizer and/or keyless system	 0
Central gateway control module	 0

DTC (6)

ABS/ESP (6 DTCs)

DTC	Description	Status
C1137-1C	Steering angle sensor power supply system error	History
C1157-1C	Power supply voltage abnormal	History
C1161-07	Pump motor circuit	History
U0401-81	CAN invalid data from ECM	History
U1082-87	Lost communication with ENG A-STOP control module	History
U1410-81	Invalid data received from ENG A-STOP control module	History

Technician Notes

2016866051



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.