



Shop: DEKRA MFC  
Tel: --  
Email: --  
Address: MFC Auction House  
Kempton Park

Report ID: MAXIA20231222102746  
Test Time: 2023-12-22 10:27:46  
Technician: Andrick

# Honda VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Honda/Brio/--

VIN: MAKDD1780FN000398

Odometer Reading: 155645km

License Plate: DZ38DRGP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

## Device information









Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V9.20

Repair Order Number: --

## System Scanned( 7 )

System	Status/DTC
Engine-PGM FI	 3
ABS/TCS/VSA	 0
SRS	 0
Gauges	 0
Body electrical	  0
IMMOBI	 0
EPS	 0

## DTC ( 3 )

### Engine-PGM FI ( 3 DTCs )

DTC	Description	Status
P0641	Sensor reference voltage A malfunction	Permanent DTC
P0651	Sensor reference voltage B malfunction	Permanent DTC
P0562	Charging system low voltage	Permanent DTC

## Technician Notes

2016210100

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.