



Shop: --  
Tel: --  
Email: --  
Address: --

Report ID: MAXIA20240502113920  
Test Time: 2024-05-02 11:39:20  
Technician: Sbu

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--  
VIN: MALA851ALJM794660

Odometer Reading: 75108  
License Plate: HJ93PPGP

## Customer Information

Name: MFC Dekra Nedbank Auction House







Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.50

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned( 6 )

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

## DTC ( 1 )

AB (Airbag) ( 1 DTC )

DTC	Description	Status
B1102:00	Battery voltage low	History

## Technician Notes

2016363150

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

