AUTEL

Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20240514145138 Test Time: 2024-05-1414:51:38

Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Atos/--

VIN: MALAF51CLNM143944

Customer Information

Name: MFC Dekra Nedbank Auction House

Device information

Scanner: MaxiSys MS906 BT

Version: V13.50

Odometer Reading: 48724km License Plate: JZ86YSGP

Tel: 0861033572

Serial Number: VB8GJCC01509

Repair Order Number: --

🔁 System Scanned(6)

System	Status/DTC
ENG (Engine)	O
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	O
AB (Airbag)	Q 4
CLU (Cluster Module)	② 0
IMMO (Immobilizer)	② 0
EPS (Motor Driven Power Steering)	O

▲ DTC (4)

AB (Airbag) (4 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B1116:00	Battery voltage unstable	History
B1329:00	Driver front impact sensor (FIS) communication error	History
B1650:00	Crash recorded in 1st stage only (Frontal - Replace SRSCM)	Active

AUTEL www.autel.com

MaxiSys MS906 BT Page 1

	_	
Hvundai/ Atos/	Test Time: 2024-05-14 14:51:38	Report ID: MAXIA20240514145138

Technician Notes

2016377847

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2