



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231229113243
Test Time: 2023-12-29 11:32:43
Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i10(PA)/--

VIN: MALAN51CLCM118661

Odometer Reading: 219623

License Plate: BZ31TRGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V13.40

Repair Order Number: --

System Scanned(5)

System	Status/DTC
ENG (Engine)	 3
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 2
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 2

DTC (7)

ENG (Engine) (3 DTCs)

DTC	Description	Status
P0011	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	Active
P0626	Generator field 'F' terminal circuit high	History
P0642	Sensor reference voltage 'A' circuit low	History

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102	Battery voltage low	History
B1334	Passenger front impact sensor (FIS) communication error	Active

EPS (Motor Driven Power Steering) (2 DTCs)

DTC	Description	Status
C1101	Battery voltage high	Active
C1272	Engine speed input fault	Active



Technician Notes

2016214157

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.