

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20/--

VIN: MALBB51BLEM607770

Odometer Reading: 137977

License Plate: CY34JNGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V13.50

Repair Order Number: --



System Scanned(7)

System	Status/DTC
ENG (Engine)	4
ESP (Electronic Stability Program)	4
AB (Airbag)	3
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
BCM (Body Control)	0



DTC (12)

ENG (Engine) (4 DTCs)

DTC	Description	Status
P0014	Exhaust camshaft position (CMP) B timing over-Advanced or system performance (Bank 1)	Pending
P0077	Intake valve control solenoid circuit high (Bank 1)	History
P0130	Oxygen sensor circuit (Bank 1 sensor 1)	Pending
P0563	System voltage high	Pending

ESP (Electronic Stability Program) (4 DTCs)

DTC	Description	Status
C1102	Battery voltage low	History
C1206	Left rear wheel speed sensor (WSS) circuit open or short	Active
C2112	Valve relay error	History
C2402	Motor electrical fault	History

AB (Airbag) (3 DTCs)

DTC	Description	Status
B1102	Battery voltage low	Active
B1346	Driver airbag (DAB) resistance too high (1st Stage)	Active
B1367	Front passenger pretensioner resistance too high	Active

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1611	CAN Timeout - Engine management system (EMS)	History

Technician Notes

2016819251

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.