



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250828125745
Test Time: 2025-08-28 12:57:45
Technician: Werner

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/Swift/--
VIN: MBHCZF63S00370234

Odometer Reading: 62398
License Plate: LF55CZGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V4.80

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (9)

System	Status/DTC
Engine/powertrain	 0
TCM	 0
ABS/ESP	 2
Airbag	 0
Instrument Panel Cluster (IPC)/meter/M&A	 2
Central gateway control module	 1
Power steering	 0
BCM	 0
Immobilizer and/or keyless system	 0

DTC (5)

ABS/ESP (2 DTCs)

DTC	Description	Status
U0126	Lost communication with steering angle sensor module	History
C1057	Power supply voltage	History

Instrument Panel Cluster (IPC)/meter/M&A (2 DTCs)

DTC	Description	Status
B1840	Vehicle speed data invalid	History
U0121	Lost communication with ABS or electronic stability program control module	History

Central gateway control module (1 DTC)

DTC	Description	Status
-----	-------------	--------



U0121-87	Lost communication with ABS or electronic stability program control module	History
----------	--	---------

Technician Notes
2016994659

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.