

Shop Name: --Tel: --Email: --Address: --

Report ID: MAXIA20250829134441 Test Time: 2025-08-29 13:44:41

Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--VIN: MDHZBAAD0Z0512704

Odometer Reading: 122386km License Plate: LY71NJGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V10.30

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine	O
ABS	Q 2
Air bag	Q 2
Meter/M&A	② 0
Electric Power Steering (EPS)/DAST 3	Q 2
BCM	Q 3
IPDM E/R	② 0

🔼 DTC (9)

ABS (2 DTCs)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past
C1105	Right rear sensor 2	Past

Air bag (2 DTCs)

DTC	Description	Status
B0001:13	Driver airbag module	Past
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (2 DTCs)

DTC	Description	Status
C1608	Control unit	Past
U1000	CAN communication circuit	Past

BCM (3 DTCs)

DTC	Description	Status
U1000	CAN communication circuit	Past

/Nissan/Datsun Go	Test Time: 2025-08-29 13	3:44:41 Report ID:	MAXIA20250829134441
B2190	Nissan anti-theft system (NATS) antenna AMP	Past	
B2193	Chain of BCM-ECM	Past	

Technician Notes 2016997079

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2