

Shop Name: --Tel: --Email: --Address: -- Report ID: MAXIA20250901143537 Test Time: 2025-09-01 14:35:37

st Time: 2025-09-01 14:35:37 Technician: Andrick

# Renault VEHICLE DIAGNOSTIC REPORT

### **Vehicle Information**

--/Renault/KWID/-- Odometer Reading: 71667 VIN: MEEBBA00600731959 License Plate: NO Re g

**Customer Information** 

Name: MFC Dekra Nedbank Auction House Tel: 0861033572

**Device information** 

Scanner: MaxiSys MS906 BT Serial Number: VB8GJCC01509

Version: V15.00 Repair Order Number: --

## System Scanned (6)

System	Status/DTC
INJ(Injection)	<b>Q</b> 2
ABS(Anti-lock braking system)	<b>②</b> 0
ABG(Airbag / pretensioners)	<b>Q</b> 3
TDB(Instrument panel)	<b>Q</b> 1
UCH(Central control unit)	<b>②</b> 0
DAV(Variable power assist steering)	<b>Q</b> 1

## Material Description ■ DTC (7)

### INJ(Injection) (2 DTCs)

DTC	Description	Status
DTC021798	Engine overheating Operation temperature too high.	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory

#### ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault Signal low	Memory
DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTC903617	Power supply voltage Circuit voltage above threshold	Memory

#### TDB(Instrument panel) (1 DTC)

DTC Description Status

AUTEL www.autel.com

MaxiSys MS906 BT

Page 1

/Renault/KWID		Test Time: 2025-09-0	1 14:35:37	Report ID:	MAXIA20250901143537
DTCC00187	CAN communication Signal missing.			Memory	
DAV(Variable po	ower assist steering) (1 DTC)				
DTC	Description			Status	
DTC560849	Computer Internal electronic failure			Memory	
Technician Not 2016998150	tes				
		Customer n	ame:		
		Techni	cian:		
		ו	Date:		
			Note:Please sa	ave a copy of t	his report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury



resulting from the use of this information.

MaxiSys MS906 BT Page 2