

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00100101465

Odometer Reading: 5530
License Plate: LL41RBGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V15.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(9)

System	Status/DTC
INJ(Injection)	 1
ABS(Anti-lock braking system)	 0
ABG(Airbag / pretensioners)	 0
TDB(Instrument panel)	 2
UCH(Central control unit)	 2
UCC(Communications unit)	  0
DAV(Variable power assist steering)	 0
GW2(Central gateway)	 0
HFM(Hands-free module)	 0

DTC (5)

INJ(Injection) (1 DTC)

DTC	Description	Status
DTC065711	Main relay control circuit Short circuit to earth.	Memory

TDB(Instrument panel) (2 DTCs)

DTC	Description	Status
DTC940213	Fuel sender circuit Open circuit	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

DTC5A607B	Under-inflated Low fluid level	Memory
DTC5A8055	Tire pressure monitor function Not configured	Memory

Technician Notes
2016996137

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.