

Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240709141438
Test Time: 2024-07-09 14:14:38
Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Avanza/Veloz/--
VIN: MHKM5EA1N0K003328

Odometer Reading: 313983
License Plate: JL89XPGP

Customer Information

Name: Dekra MFC AUCTION HOUSE









Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
EFI	 2
ABS	 8
A/B	 9
Combination meter	 3
Body	 0
Electric power steering (EPS)	 3
Combination switch	 0
IMB	 1

DTC (26)

EFI (2 DTCs)

DTC	Description	Status
P0504	Stop lamp switch system fault	Current
P0504	Stop lamp switch system fault	History

ABS (8 DTCs)

DTC	Description	Status
C0200	FR wheel open wire/shorted	Current
C0210	RR wheel open wire/shorted	Current
C1202	Master reservoir level	Current
C1235	Abnormal cycle of FR wheel	Current



C1236	Abnormal cycle of FL wheel	Current
C1241	Voltage dropped/over	Current
C1249	Stop lamp switch open wire	Current
U0100	Communication with electronic fuel injection (EFI) abnormal	Current

A/B (9 DTCs)

DTC	Description	Status
B1801	Driver seat frontal collision squib circuit open	Current
B1806	Passenger seat frontal collision squib circuit open	Current
B1901	Right front seat pretensioner circuit open	Current
B1906	Left front seat pretensioner circuit open	Current
B1612	R side front sensor communication interruption	History
B1801	Driver seat frontal collision squib circuit open	History
B1806	Passenger seat frontal collision squib circuit open	History
B1901	Right front seat pretensioner circuit open	History
B1906	Left front seat pretensioner circuit open	History

Combination meter (3 DTCs)

DTC	Description	Status
U0142	Communication with ITC	History
U0100	Communication with electronic fuel injection (EFI)	History
U0129	Communication with ABS/VSC	History

Electric power steering (EPS) (3 DTCs)

DTC	Description	Status
C1552	PIG voltage abnormality	History
U0100	CAN communication error (EFI)	History
C1557	Overheat preventive control current limit history	History

IMB (1 DTC)

DTC	Description	Status
B2789	Communication faulty (no reply)	Current

Technician Notes

2016448200

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

