

Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20241030100535
Test Time: 2024-10-30 10:05:35
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Avanza/Veloz/--
VIN: MHKM5FA2N0K013108

Odometer Reading: 164094
License Plate: KBC808MP

Customer Information

Name: Dekra MFC AUCTION HOUSE









Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V11.10

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(8)

System	Status/DTC
EFI	 0
ABS	 4
A/B	 1
Meter	 0
Body	 0
EPS	 0
Combi SW	 0
IMB	 0

DTC (5)

ABS (4 DTCs)

DTC	Description	Status
C1233	Yaw rate sensor (YRS) open/short	Current
C1241	Voltage dropped/over	Current
C1245	G sensor signal abnormal	Current
U0100	Communication with electronic fuel injection (EFI) abnormal	Current

A/B (1 DTC)

DTC	Description	Status
B1806	Passenger seat frontal collision squib circuit open	History



Technician Notes

2016591430

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.