

Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

٧	'e	h	ic	le	In	fo	rm	na	tic	n	
	-	•••									

/Mercedes-Benz/176.052 - Mercedes-AMG A 45 4MATIC Sedan/	Odometer Reading: 83565km
VIN: WDD1760522J192630	License Plate: HJY307FS
Customer Information	
Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE	Tel: 0861033572
Device information	
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01482
Version: V18.80	Repair Order Number:

🔁 System Scanned(39)

System	Status/DTC
ECM(Engine Control Unit)	S 4
TCM(Transmission Control Unit)	O
ESP(Electronic Stability Program Braking System)	Q 1
SRS(Supplemental Restraint System Control Unit)	O
KI(Instrument Cluster)	Q 1
EPB(Electric Parking Brake)	Q 1
SAM(Signal Acquisition Control Unit)	🔇 6
LIN:AISP(Interior Rearview Mirror)	O
LIN:BSN(Battery Sensor)	O
LIN:DBE-1_2(Sunroof Control Unit)	Q 1
LIN:OBF(Upper Control Panel)	O
LIN:PSMD(Driver Side Electric Seat Adjustment Control Unit)	O
LIN:SHM(Seat Heating)	3
LIN:VCS-1(Light Sensor)	O
EZS(Electronic Ignition Lock Control Unit)	Q 1
ES(Electric Power Steering)	O
KLA(Air Conditioner Control Unit)	Q 1



	O
	O
	O
ADAS	Q 1
ADAS	Q 1
	o
ADAS	O
AØAS	O
	Q 1
	O
	O
	Q 1
	O
	Q 1
	O
	O
	O
AØAS	O
	3
	O
	O
	O

🔼 DTC (31)

ECM(Engine Control Unit) (4 DTCs)				
DTC	Description	Status		
P13C700	The exhaust flap has an electrical fault or an open circuit.	Stored		

Report ID: MAXIA20240202150153

P1CE200	The ECO start/stop function has detected excessively low engine speed.	Stored			
P008700	The fuel pressure in the system is too low.	Stored			
P012800	The coolant temperature is below the coolant thermostat specified temperature.	Stored			
ESP(Electronic	Stability Program Braking System) (1 DTC)				
DTC	Description	Status			
C073300	'AP26 (Additional battery)' is faulty.	Active and stored			
KI(Instrument C	luster) (1 DTC)				
DTC	Description	Status			
B228200	The value of the main odometer reading is implausible.	Stored			
EPB(Electric Pa	rking Brake) (1 DTC)				
DTC	Description	Status			
P0B0200	Shutoff due to undervoltage	Stored(Event codes)			
SAM(Signal Acq	uisition Control Unit) (6 DTCs)				
DTC	Description	Status			
P25567B	Sensor 'Coolant level' has a malfunction. The fluid level is too low.	Active and stored			
B181E64	The sensor for the engine hood has a malfunction. There is an implausible signal. If there is no specific customer complaint, ignore the fault.	Stored			
B11C116	The additional battery has a malfunction. The limit value for electrical voltage has not been attained.	Active and stored			
B11C113	The additional battery has a malfunction. There is an open circuit.	Active and stored			
B11C11B	The additional battery has a malfunction. The limit value for resistance has been exceeded.	Stored			
B11C118	The additional battery has a malfunction. The limit value for current has not been attained.	Stored			
LIN:DBE-1_2(Sunroof Control Unit) (1 DTC)					
DTC	Description	Status			
B22A31C	'Overhead control panel' has a malfunction. The voltage value is outside the permissible range.	Stored(Event codes)			
LIN:SHM(Seat Heating) (7 DTCs)					
DTC	Description	Status			
P25567B	Sensor 'Coolant level' has a malfunction. The fluid level is too low.	Active and stored			

Report ID: MAXIA20240202150153

B181E64	The sensor for the engine hood has a malfunction. There is an implausible signal. If there is no specific customer complaint, ignore the fault.	Stored			
B11C116	The additional battery has a malfunction. The limit value for electrical voltage has not been attained.	Active and stored			
B11C113	The additional battery has a malfunction. There is an open circuit.	Active and stored			
B11C11B	The additional battery has a malfunction. The limit value for resistance has been exceeded.	Stored			
B11C118	The additional battery has a malfunction. The limit value for current has not been attained.	Stored			
B22A31C	'Overhead control panel' has a malfunction. The voltage value is outside the permissible range.	Stored(Event codes)			
EZS(Electronic le	gnition Lock Control Unit) (1 DTC)				
DTC	Description	Status			
B21DC01	The additional battery has a malfunction. There is a general electrical fault.	Active and stored			
KLA(Air Conditio	oner Control Unit) (1 DTC)				
DTC	Description	Status			
9A9E11	The output for external power supply of the pressure sensor has a malfunction. There is a short circuit to ground.	Stored			
SW-SW-L(Left Headlamp Control Unit) (1 DTC)					
DTC	Description	Status			
B284613	Please refer to vehicle service manual.	Active and stored			
SW-SW(Headlan	np Control Unit) (1 DTC)				
DTC	Description	Status			
B284613	Left cornering illumination fault - open circuit	Active and stored			
DMFL(Left Front Door Control Unit) (1 DTC)					
DTC	Description	Status			
B1DD015	The output for the mirror heater has a malfunction. There is a short circuit to positive or an open circuit.	Stored			
ZAN(Center Display Control Unit) (1 DTC)					
DTC	Description	Status			
C147	Communication with the 'Head unit' has a malfunction.	Stored(Event codes)			
RBTMFR(Passenger Seat Belt Tensioner Control Unit) (1 DTC)					
DTC	Description	Status			
640500	Software error	Stored			
	SUILWATE EITUI	Storeu			

Report ID: MAXIA20240202150153

FSCU(Fuel Pump Control Unit) (3 DTCs)

DTC	Description	Status
P008700	The fuel pressure in the system is too low.	Stored
P062700	The output for the fuel pump has an electrical fault or open circuit.	Stored
P008A00	The pressure in the fuel low pressure circuit is too low.	Stored

Technician Notes

2016253209

Customer name:

Technician: _____

Date: ____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.