



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231222145054
Test Time: 2023-12-22 14:50:54
Technician: Werner

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/EcoSport/--

VIN: WF01XXERK1JY36417

Odometer Reading: 85662

License Plate: HN15RGGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V8.20

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(14)

System		Status/DTC
PCM (Powertrain Control Module)		 3
ABS (Anti-lock Brake System)		 0
RCM (Restraint Control Module)		 0
IPC (Instrument Panel Control Module)		 3
ACM (Audio Control Module)		 0
APIM (Accessory Protocol Interface Module)		 0
BdyCM(Body control module)		 0
DDM (Driver Door Module)		 0
GWM (Gateway Module A)		 0
HVAC (Heating Ventilation Air Conditioning)		 0
PAM (Parking Aid Module)		 0
PDM (Passenger Door Module)		 0
PSCM (Power Steering Control Module)		 0
SCCM (Steering Column Control Module)		 0

DTC (6)

PCM (Powertrain Control Module) (3 DTCs)

DTC	Description	Status
P061A:00-28	Internal Control Module Torque Performance	CMDTCs
P06E9:00-28	Engine Starter Performance	CMDTCs



U0256:00-28

Lost Communication With Front Controls Interface Module A

CMDTCs

IPC (Instrument Panel Control Module) (3 DTCs)

DTC	Description	Status
P0460:11-08	Fuel Level Sensor A Circuit	CMDTCs
U0146:00-08	Lost Communication With Serial Data Gateway A	CMDTCs
U0199:00-08	Lost Communication With Door Control Module A	CMDTCs

Technician Notes

2016211827

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.