

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/Jetta TSI/--  
 VIN: WVGZZZ16ZHM000572

Odometer Reading: 166739  
 License Plate: HM50HKGP

## Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE
















Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V19.00

Serial Number: VB8GJCC01482  
 Repair Order Number: --

## System Scanned ( 15 )

System	Status/DTC
01 - Engine Control Module 1	 7
02 - Transmission electronics	 2
03 - Brakes 1	 2
08 - Air Conditioning	 0
09 - Electronic central electric	 5
15 - Airbag	 1
16 - Steering column electronics	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
42 - Driver's door electronics	 3
44 - Power Steering	 0
52 - Passenger's door electronics	 3
5F - Information electronics 1	 1
61 - Battery Regulation	 1

## DTC ( 26 )

### 01 - Engine Control Module 1 ( 7 DTCs )

DTC	Description	Status
-----	-------------	--------

P305400	Starter does not turn Mechanically blocked or electrical malfunction	Active/static
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030400	Cylinder 4 Misfire detected	Passive/Sporadic
P125000	Fuel level too low	Active/static
P044100	EVAP Emission Contr.Sys.Incorrect Purge Flow	Passive/Sporadic
P042000	Catalyst system (bank 1) Efficiency below lower limit	Passive/Sporadic

## 02 - Transmission electronics ( 2 DTCs )

DTC	Description	Status
P189A:00/06 298:000	Clutch 1 Clearance too small -	Passive/Sporadic
P177B:07/06 011:007	Clutch 1 Tolerance limit reached - Short circuit to ground	Passive/Sporadic

## 03 - Brakes 1 ( 2 DTCs )

DTC	Description	Status
01826:000	Steering angle sensor, voltage supply terminal 30 -	Passive/Sporadic
01325:004	Tire Pressure Monitoring Control Module - No signal/communication	Passive/Sporadic

## 09 - Electronic central electric ( 5 DTCs )

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
01134:002	Alarm horn - Lower limit not reached	Passive/Sporadic
01598:011	Drive battery voltage - Open circuit	Passive/Sporadic
02394:010	Bulb for left front parking light - Open circuit/short circuit to B+	Passive/Sporadic

## 15 - Airbag ( 1 DTC )

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

**16 - Steering column electronics ( 1 DTC )**

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

**42 - Driver's door electronics ( 3 DTCs )**

DTC	Description	Status
B11EC54	Motor for front window regulator No basic setting	Passive/Sporadic
B11FD01	Turn signal in exterior rear-view mirror Electrical error	Passive/Sporadic
B11EE54	Motor for rear window regulator No basic setting	Passive/Sporadic

**52 - Passenger's door electronics ( 3 DTCs )**

DTC	Description	Status
B11EC54	Motor for front window regulator No basic setting	Passive/Sporadic
B11FD01	Turn signal in exterior rear-view mirror Electrical error	Passive/Sporadic
B11EE54	Motor for rear window regulator No basic setting	Passive/Sporadic

**5F - Information electronics 1 ( 1 DTC )**

DTC	Description	Status
U140000	Function restriction Caused by low voltage	Passive/Sporadic

**61 - Battery Regulation ( 1 DTC )**

DTC	Description	Status
01598:003	Drive battery voltage - mechanical malfunction	Passive/Sporadic

## Technician Notes

2016221731

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.