

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: WVWZZZ60ZDT032441

Odometer Reading: 187940km
License Plate: CK15MKGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V23.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	 1
03 - Brakes 1	 0
09 - Electronic central electric	 3
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 1
44 - Power Steering	 0
56 - Radio	 1

DTC (7)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
16711:000	Knock Sensor 1 Circ. Low Input	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
02604:000	Message 'Voltage supply too low' from Power Steering Control Module	Passive/Sporadic
03591:006	Signal horn activation - Short circuit to B+	Passive/Sporadic
03591:011	Signal horn activation - Open circuit	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
U112200	Data bus message implausible	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
01305:004	Databus Infotainment - No signal/communication	Passive/Sporadic

Technician Notes

2016998056

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.