



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240411101038
Test Time: 2024-04-11 10:10:38
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AM/AN - Golf Sports van 2014 >/--
VIN: WVVZZZAUZEW271412

Odometer Reading: 139822km
License Plate: N o n e n u m b e r p l a t e

Customer Information

Name: Dekra MFC AUCTION HOUSE

















Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V20.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(15)

System	Status/DTC
01 - Engine Control Module 1	 11
02 - Transmission electronics	 1
03 - Brakes 1	 6
08 - Air Conditioning	 5
09 - Electronic central electric	 12
15 - Airbag	 0
16 - Steering column electronics	 2
17 - Instrument cluster	 2
19 - Gateway	 4
42 - Driver's door electronics	 5
44 - Power Steering	 2
52 - Passenger's door electronics	 4
55 - Headlight Regulation	  4
5F - Information electronics 1	 3
A9 - Structure-Borne Sound Actuator	 2

DTC (63)

01 - Engine Control Module 1 (11 DTCs)

DTC	Description	Status
-----	-------------	--------



>

P0E7B00	Coolant Bypass Valve 'B' Control Circuit/Open	Passive/Sporadic
P0E7C00	Coolant Bypass Valve 'B' Control Circuit Low	Passive/Sporadic
P16C100	Heater support pump ,Open circuit	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
P056200	System Voltage ,Low Voltage	Passive/Sporadic
P052400	Engine Oil Pressure Too Low	Active/static
P150A00	Engine Off Timer Performance	Passive/Sporadic
P256300	Turbocharger boost control position sensor circuit range/performance	Passive/Sporadic
P001700	Crankshaft Position (CKP)-Camshaft Position (CMP) ,Correlation (bank 1 sensor B)	Passive/Sporadic
P034100	Camshaft Position (CMP) sensor circuit ,Range/performance	Passive/Sporadic

02 - Transmission electronics (1 DTC)

DTC	Description	Status
P056200	System Voltage ,Low Voltage	Passive/Sporadic

03 - Brakes 1 (6 DTCs)

DTC	Description	Status
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic
U140100	Function restriction ,Caused by excessive voltage	Passive/Sporadic
B116816	Steering angle sensor ,Voltage too low	Passive/Sporadic
U112200	Data bus message implausible	Passive/Sporadic
C114602	TPMS ,Signal error	Passive/Sporadic
C10D700	Comfort restriction	Passive/Sporadic

08 - Air Conditioning (5 DTCs)

DTC	Description	Status
B10ABF0	Refrigerant pressure ,Below lower limit	Active/static
B10AF04	Air quality sensor ,Faulty	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic
B10CE00	Blower reduction by energy management	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (12 DTCs)

DTC	Description	Status
B121715	Left low beam headlamp bulb ,Circuit open or short to positive	Passive/Sporadic
B121815	Right low beam headlamp bulb ,Circuit open or short to positive	Passive/Sporadic
B12ECF2	LED module for left DRL and parking lamp ,Power supply circuit open or short to positive	Passive/Sporadic
B12EDF2	LED module for right DRL and parking lamp ,Power supply circuit open or short to positive	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic
B103F1B	Exterior temperature sensor ,Resistance too high	Passive/Sporadic
B126301	Tank lid unlock activation ,Electrical error	Active/static
B131DF7	Sirens / alarm horn for anti-theft warning system ,No release by immobilizer	Passive/Sporadic
B131DF5	Sirens/alarm horn for anti-theft warning system ,Voltage supply below lower limit	Passive/Sporadic
B131D04	Sirens/alarm horn for anti-theft warning system ,Faulty	Passive/Sporadic
U112100	Data bus message missing	Active/static

16 - Steering column electronics (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic
B116229	Gear selector lever park position lock switch ,Range/performance	Active/static

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

19 - Gateway (4 DTCs)

DTC	Description	Status
U101D00	Lost communication with power steering control unit	Passive/Sporadic
U107000	Automatic high beam assist control unit ,No communication	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U141100	Battery terminal recognition ,Open circuit	Passive/Sporadic

42 - Driver's door electronics (5 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B122D29	Locking unit for central locking ,Range/performance	Passive/Sporadic
B131FF5	Driver side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B131FF4	Driver side rear window regulator ,Voltage supply above upper limit	Passive/Sporadic
B132102	Driver side rear window regulator motor ,Signal fault	Passive/Sporadic

44 - Power Steering (2 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

52 - Passenger's door electronics (4 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B122D29	Locking unit for central locking ,Range/performance	Passive/Sporadic
B1320F5	Passenger side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B1320F4	Passenger side rear window regulator ,Voltage supply above upper limit	Passive/Sporadic

55 - Headlight Regulation (4 DTCs)

DTC	Description	Status
U10BA00	Local data bus ,No communication	Passive/Sporadic
C108231	Right headlamp power output stage ,No signal	Passive/Sporadic
B121700	Left low beam headlamp bulb	Passive/Sporadic
B121800	Right low beam headlamp bulb	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic
B1297F5	Multimedia system display unit 1 ,Below supply voltage lower limit	Passive/Sporadic

A9 - Structure-Borne Sound Actuator (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic

Technician Notes
2016337113

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.