

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AM/AN - Golf Sports van 2014 >/--

VIN: WVGZZZAUZJW169283

Odometer Reading: 208004km

License Plate: HK41BWGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V19.00

Repair Order Number: --



System Scanned(14)

System	Status/DTC
01 - Engine Control Module 1	10
03 - Brakes 1	4
08 - Air Conditioning	2
09 - Electronic central electric	3
15 - Airbag	0
16 - Steering column electronics	0
17 - Instrument cluster	2
19 - Gateway	1
20 - High beam assistant	0
42 - Driver's door electronics	1
44 - Power Steering	3
52 - Passenger's door electronics	2
5F - Information electronics 1	0
76 - Parking assistance	0



DTC (28)

01 - Engine Control Module 1 (10 DTCs)

DTC	Description	Status
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P233700	Cylinder 2 above knock threshold	Passive/Sporadic

P016900	Incorrect fuel composition	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030200	Cylinder 2 Misfire detected	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P125000	Fuel level too low	Active/static
P042000	Catalyst system (bank 1) Efficiency below lower limit	Passive/Sporadic

03 - Brakes 1 (4 DTCs)

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic
C102D00	Tire pressure warning	Active/static
C110029	Hydraulic assistance Range/performance	Passive/Sporadic
C10C2F0	Function restriction Emergency brakes unavailable	Active/static

08 - Air Conditioning (2 DTCs)

DTC	Description	Status
B10ABF0	Refrigerant pressure Below lower limit	Active/static
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
B121815	Right low beam headlamp bulb Circuit open or short to positive	Active/static
B133029	Anti-theft alarm system sensor Range/performance	Passive/Sporadic
B131DF7	Sirens / alarm horn for anti-theft warning system No release by immobilizer	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

B104C29 Key
Range/performance

Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B131FF5	Driver side rear window regulator Voltage supply below lower limit	Passive/Sporadic

44 - Power Steering (3 DTCs)

DTC	Description	Status
C10AC07	Steering mechanical malfunction	Active/static
U101100	Supply voltage Voltage too low	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic

52 - Passenger's door electronics (2 DTCs)

DTC	Description	Status
B148701	Motor for window regulator Electrical error	Active/static
B1320F5	Passenger side rear window regulator Voltage supply below lower limit	Passive/Sporadic

Technician Notes

2016204986

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.