DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**

*MFC Auction House*
*M57 Pretoria Rd, Glenmarais, KEMPTON PARK*
*Gauteng*

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








## Assignment

| | | | |
|---|---|---|---|
| Client | MFC Auction House | Inspection Location | MFC<br>M57 Pretoria Road - 1619<br>Kempton Park - GT |
| Requested Date | 09/11/2026 | | |
| Inspection Date | 09/11/2026 | | |

## Vehicle Data

| | | | |
|---|---|---|---|
| Vehicle Type | PASSENGER VEHICLE | Registered Owner | MFC AUCTION HOUSE |
| Manufacturer | VOLKSWAGEN | Registration Number | KH22LGGP |
| Model | POLO VIVO 1.6 COMFORTLINE 5-DR TIPTRONIC [2021-2023] | Register Number | |
| | | Date Of First Licensing | |
| VIN | AAVZZZ6RZNU004252 | Last COR | |
| Engine Number | | License Expiry Date | 31/03/2026 |
| Doors | 5 | Power / Displacement | |
| Color | BROWN | Paint Finish | TWO COAT METALLIC |
| Year Model | 2021 | Fuel | PETROL |
| Km Reading | 89,921 KM | Transmission | AUTOMATIC |
| Cab / Body Type | HATCHBACK | | |

## Vehicle Options & Accessories

**Items**

## VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**



| Damage | Repair Way |
|---|---|
| Engine Management Lights Set | Repair |
| Headlight Right Damaged | Replace |
| Steering Wheel Trim Damaged | Repair |
| Front Bumper Damaged | Repair |
| Bonnet Damaged | Repair |
| Front Fender Left Damaged | Repair |
| Front Fender Right Damaged | Repair |
| Rear Fender Left Damaged | Repair |
| Rear Fender Right Damaged | Repair |
| Door Front Left Damaged | Repair |
| Door Front Right Damaged | Repair |
| Door Rear Left Damaged | Repair |
| Door Rear Right Damaged | Repair |
| Boot Lid / Hatch door Damaged | Repair |
| Rear bumper Damaged | Repair |
| Warning light illuminated | Repair |

## Brakes

### Brake Test Results

| | Left | Right | | |
|---|---|---|---|---|
| | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s²] |
| **Front** | 3.33 | 2.9 | - | |
| **Rear** | 1.33 | 1.95 | - | |
| **Emergency / Parking** | 1.09 | 1.59 | - | |

## Tyres and Rims

### Tyre Specification & Measurement

| | Size | Load/Speed Index | Manufacture | Model | Type* | Production Date | Tread Depth (mm) |
|---|---|---|---|---|---|---|---|
| **Front Left** | 185/60R15 | 84H | Continental | Contipremiu | V | 3123 | 2 mm |
| **Front Right** | 185/60R15 | 84H | Continental | Contipremiu | V | 2823 | 2 mm |
| **Rear Left** | 185/60R15 | 84H | Continental | Contipremiu | V | 1723 | 4 mm |
| **Rear Right** | 185/60R15 | 84H | Continental | Contipremiu | V | 2721 | 3 mm |

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**

## Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System | Code | Description | Status |
|---|---|---|---|---|
| 1 | ELECTRONIC CENTRAL ELECTRIC | 01758 | LAMPS FOR BRAKE LIGHTS - OPEN CIRCUIT | |

## Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: automatic Park lockout not releasing.

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**




FRONT RIGHT CORNER




REAR LEFT CORNER




90 DEGREE FRONT




90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**



INTERIOR (FRONT DRIVER DOOR)



Automatic.



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER




LICENSE DISC




VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**



ENGINE 1




Undercarriage front.




Undercarriage rear.



Oil cap and dipstick.



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT


**Report No:**
**2017323388**
**DATE**
**09/11/2026**




LR TYRE TREAD




RR TYRE TREAD




Brake test.



Diagnostic Report page 1




Diagnostic Report page 2



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**



Headlight Right




Front Bumper



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**



Door Front Left



Door Rear Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252

DEKRA

# CONDITION REPORT

**Report No:**
**2017323388**
**DATE**
**09/11/2026**



Door Front Right



Rear Fender Right



Front Fender Right



Engine Management Lights



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZNU004252