DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/09/2025		
Inspection Date	09/09/2025		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KB32YNGP
Model	POLO 1.0 TSI 70KW TRENDLINE 5-DR [2019-2021]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAWZLU067392	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT METALLIC
Year Model	2020	Fuel	PETROL
Km Reading	119,502 KM	Transmission	MANUAL
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025





Damage	Repair Way
Central Air Vent Defective	Repair
Switch Electrical Window Winder front left Damaged	Replace
Switch Electrical Window Winder front right Damaged	Replace
Headlight Left Scratched	Replace
Seat Front Right Damaged	Repair
Seat Belt Front Right Damaged	Replace
Hood Lining Damaged	Replace
Carpet Front Damaged	Repair
Side Mirror Left Residual Traces of Repair	Replace
Front Bumper Damaged	Repair
A • Pillar Left Dented	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Damaged	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Roof Dented	Repair
Tyre Front Right Damaged	Replace
Tyre Rear Left Worn	Replace
Belly plates Defective	Repair
Deceleration service brake defective	Repair
Body and Exterior	Poor residual traces of repair on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Body and Exterior	Dents and scratches on some body panels
Body and Exterior	Signs of hail damage on some body panels
Body and Exterior	Some body panels misaligned

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.21	1.82	-	
Rear	1.22	1.42	-	
Emergency / Parking	0.71	0.88	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No: 2017006555
DATE 09/09/2025

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65 R14	82H	Durun	L919	V	4120	1 mm
Front Right	185/65 R14	86H	Zextour	Comfort	V	2623	0 mm
Rear Left	185/65 R14	86H	Roadking	Argos	V	2022	0 mm
Rear Right	185/70 R14	88T	Hilo	Genesys	V	3823	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P06E900	ENGINE STARTER PERFORMANCE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Interior: Vehicle interior dirty and some panels scratched
Tyres and Rims: Spare wheel missing.Front and rear tyre sizes different.
Undercarriage: Belly plates scratched.Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025




Oil cap and dipstick




Manual Transmission



Spare wheel Accessories



Deceleration service brake rep



Brake and shock absorber repor



Diagnostic report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392


DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



Diagnostic report page 2



Diagnostic report page 3



Front chassis



Rear chassis



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



VIN PLATE OR STICKER



ENGINE 1



Front Bumper



Front Bumper



Water level



Seat Belt Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



Hood Lining



Carpet Front



Switch Electrical Window Winder front right



Switch Electrical Window Winder front left



Seat Front Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



Door Rear Right



Front Fender Right




Rear bumper



Rear bumper



Inner Boot Floor Pan and Spare Wheel Well



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



Rear Fender Left



Door Rear Left



Switch Electrical Window Winder front left



Headlight Left



Central Air Vent



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



Sill Panel Left



Belly plates



Belly plates



Belly plates



Tyre Front Right



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392

DEKRA

CONDITION REPORT

Report No:
2017006555
DATE
09/09/2025



Roof



Roof




Water level



Side Mirror Left



A • Pillar Left



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU067392