DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park - GT**
Requested Date	**26/03/2024**		
Inspection Date	**26/03/2024**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC AUCTION HOUSE**
Manufacturer	**VOLKSWAGEN**	Registration Number	**KK84HDGP**
Model	**POLO TSI**	Register Number	
VIN	**AAVZZZAWZNU029474**	Date Of First Licensing	
Engine Number		Last COR	
Doors	**5**	License Expiry Date	**29/02/2024**
Color	**SILVER**	Power / Displacement	
Year Model		Paint Finish	**TWO COAT METALLIC**
Km Reading	**62,820 KM**	Fuel	**PETROL**
Cab / Body Type	**HATCHBACK**	Transmission	**MANUAL**

Vehicle Options & Accessories

Items

VEHICLE INSPECTION




Damage	Repair Way
Engine Management Lights Set	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Rear Fender Left Damaged	Replace
Door Front Left Damaged	Repair
Door Rear Left Damaged	Repair
Rear bumper Damaged	Repair
Vehicle electronics malfunctioning.	Repair
Vehicle aircon control unit loose	Repair

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.47	3.35	-	
Rear	0.66	0.15	-	
Emergency / Parking	1.35	0.62	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Falken	Radial	V	2221	2 mm
Front Right	185/65R15	88H	Falken	Radial	V	2321	1 mm
Rear Left	185/65R15	88H	Falken	Radial	V	2221	3 mm
Rear Right	185/65R15	88H	Falken	Radial	V	2221	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: SIGNS OF REPAIR WORK DONE TO SOMEBODY PANELS. POOR ALIGNMENT TO SOME BODY PANELS. ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

VIN: AAVZZZAWZNU029474
Report No: 2016318721
2 / 8
DATE
26/03/2024


FRONT RIGHT CORNER


REAR LEFT CORNER


90 DEGREE FRONT


90 DEGREE REAR


90 DEGREE RIGHT


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721
VIN: AAVZZZAWZNU029474
DATE
26/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE 26/03/2024

VIN: AAVZZZAW[redacted]



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



Oil cap and dipstick



Undercarriage front.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

VIN: AAVZZZAWZNU029474

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

VIN: AAVZZZAWZNU029474



Undercarriage rear.



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

VIN: AAVZZZAWZNU029474

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024



VIN PLATE OR STICKER



LICENSE DISC



SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



DIAGNOSTIC REPORT PAGE 3

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024



Water level



Front Bumper



Front Bumper



Bonnet



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024



Door Front Left



Rear bumper



Rear bumper



Engine Management Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016318721

DATE
26/03/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za