DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	03/09/2026		
Inspection Date	03/09/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	ISUZU	Registration Number	KXN963MP
Model	D-MAX 1.9 DDI HR L DSL PU AT [2022-2023]	Register Number	
VIN	ACVTFR87JMD135626	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2023	Paint Finish	C - COMMON
Km Reading	55,147 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026





Damage	Repair Way
Seat Front Right Damaged	Repair
Front Bumper Paintwork • Chipmarks	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Tailgate Paintwork • Scratched	Repair
Battery warning light illuminated	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.46	3.96	-	
Rear	3.52	3.59	-	
Emergency / Parking	3.03	2.37	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/65R17	110H	Dunlop	Grandtrek	V	1924	4 mm
Front Right	255/65R17	110H	Dunlop	Grandtrek	V	0224	4 mm
Rear Left	255/65R17	110H	Dunlop	Grandtrek	V	4322	4 mm
Rear Right	255/65R17	110H	Dunlop	Grandtrek	V	4322	2 mm
Spare	255/65R17	110H	Dunlop	Grandtrek	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	IBS(INTELLIGENT BATTERY SYSTEM)	P058B_00	CURRENT DETECTION	PRESENT

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, EXTERIOR, AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026



INTERIOR (FRONT DRIVER DOOR)




DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



AUTOMATIC GEAR LEVER



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026



LR TYRE TREAD



RR TYRE TREAD



ENGINE 1



ENGINE 2



CHASSIS



OIL CAP AND DIPSTICK

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026




COOLANT BOTTLE




SPARE WHEEL




LICENSE DISC



VIN PLATE OR STICKER



SHOCK AND BRAKE TEST REPORT



DIAGNOSTIC REPORT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026




DIAGNOSTIC REPORT



Water level



Seat Front Right



Front Fender Right



Door Front Right



Rear Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626

DEKRA

CONDITION REPORT

Report No:
2017293883
DATE
03/09/2026



Front Bumper



Front Bumper



Door Front Left



Rear Fender Left



Tailgate

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ACVTFR87JMD135626