DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	13/11/2026		
Inspection Date	13/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	CHEVROLET	Registration Number	KMP255MP
Model	SPARK 1.2 LS 5-DR [2012-2013]	Register Number	
VIN	ADMMF48DLC4627636	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	BLUE	Power / Displacement	
Year Model	2012	Paint Finish	M - METALLIC
Km Reading	207,500 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No: 2017325354
DATE 13/11/2026



Damage	Repair Way
Engine Oil Leak	Repair
Expansion Bottle Defective	Replace
Water level Insufficient	Repair
Hooter Defective	Repair
Center Console / Cubbyhole + Lid Damaged	Repair
Tail Light Right Damaged	Replace
Door Handle Front Right Malfunction	Repair
Door Handle Rear Right Malfunction	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Clutch Operation Insufficient	Repair
Body exterior	Vehicle got minor scratches, stone chips and dents
Body exterior	Signs of spray work done on some body panels
Airbag light on	Repair
Brakes	No brake test done due to no clutch
Boot not opening can not see spare wheel	Repair
R/F fender liner damage	Replace
R/R tire deferred size	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/65R14	79T	Lanvigator	Comfort	V	2025	3 mm
Front Right	165/65R14	79T	Lanvigator	Comfort	V	2125	3 mm
Rear Left	165/65R14	79T	Lanvigator	Comfort	V	2125	3 mm
Rear Right	185/65R14	86T	General	Altimax	V	0716	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CURRENT	B0012:0D	STEERING WHEEL AIRBAG DEPLOYMENT LOOP HIGH RESISTA	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR, MINOR DENTS AND SCRATCHES NOTED ON VEHICLE BODY, EXTERIOR, INTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026



Oil cap and dipstick



Expention bottle




Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636


DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



ADDITIONAL 11



Expansion Bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026



Water level



Door Handle Front Right




Door Handle Rear Right



Door Handle Rear Right



Clutch Operation



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636

DEKRA

CONDITION REPORT

Report No:
2017325354
DATE
13/11/2026



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636


DEKRA

CONDITION REPORT


Report No:
2017325354
DATE
13/11/2026



Front Fender Left



Rear bumper



Rear bumper



Engine



Center Console / Cubbyhole + Lid



Hooter

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4627636