DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572








Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	11/11/2026		
Inspection Date	10/11/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	KNP595MP
Model	RANGER 2.2 TDCI XL 4X4 DSL PU [2017-2020]	Register Number	
VIN	AFANXXMJ2NJT69016	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/05/2025
Color	WHITE	Power / Displacement	
Year Model	2018	Paint Finish	TWO COAT UNI
Km Reading	220,038 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	
Hoses Defective	Replace
Under bonnet insulation cover Damaged	Repair
Air Conditioner Insufficient	Repair
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Door Panel Front Left Damaged	Repair
Door Panel Front Right Cracked	Repair
Door Sealing Rubber Front Right Damaged	Replace
Dash Padding Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Damaged	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Tailgate Damaged	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Damaged	Repair
Load Body Damaged	Repair
Windscreen Cracked	Replace
Tie Rod End left Damaged	Replace
Tie Rod End right Cracked	Replace
Steering Rack Boot Left Leak	Replace
Steering Rack Boot Right Leak	Replace
Rebound Rubber Front Axle Left Damaged	Replace
Rebound Rubber Front Axle Right Damaged	Replace
Ball Joint(s) Front Axle Left Damaged	Replace
Ball Joint(s) Front Axle Right Damaged	Replace
Mounting Rubber(s) Rear Axle Left Damaged	Replace
Mounting Rubber(s) Rear Axle Right Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Rim Front Left Dented	Repair
Rim Front Right Scratched	Repair
Bolt(s) / Nut(s) Front Wheel Right Damaged	Replace
Chassis Damaged	Repair
Engine to silencer pipe Loose / Excessive Play	Repair
Catalytic converter Missing	Replace
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair
Differential Oil Leak	Repair
Radiator Cradle Damaged	Repair
Brakes Malfunction	Repair
Engine Noise Excessive	Repair
Engine Smoke Excessive	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026

Damage	Repair Way
Clutch Operation Noisy	Repair
Left side mirror damaged	Replace
Rear right tyre regrooved	Replace
Loose wiring on rear left side of undercarriage	Replace
Gear knob damaged	Replace
Rear left and right tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65 R17	112T	Bridgestone	Dueler	V	4722	0 mm
Front Right	265/65 R17	112T	Bridgestone	Dueler	V	4722	0 mm
Rear Left	265/65 R17	112S	Bridgestone	Dueler	V	2218	0 mm
Rear Right	255/65 R17	110T	Goodyear	Wrangler	V	3116	0 mm
Spare	245/75 R16	111S	Jk tyre	Elanzo	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	P0299:00-68	TURBOCHARGER/SUPERCHARGER A UNDERBOOST CONDITION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Signs of rodent in engine bay.
Interior: Vehicle interior dirty and panels scratched.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026

Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.
Undercarriage: Signs of surface rust on undercarriage.
Road Test: Vehicle unsafe to drive

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT


Report No:
2017323661
DATE
10/11/2026



Shock absorber report



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016


DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Rear chassis



Front chassis



Loose wiring on undercarriage

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Spare wheel Accessories



Left side mirror



Oil cap and dipstick



Seat Front Right



Door Sealing Rubber Front Right



Door Panel Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Front Fender Right



Front Bumper



Front Bumper



Grill



Grill



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Windscreen



Front Fender Left




Headlight Left



Headlight Right



Water level



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016


DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Engine Wiring



Engine Wiring



Under bonnet insulation cover



Under bonnet insulation cover



Hoses



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Bolt(s) / Nut(s) Front Wheel Right



Rim Front Right



Rear Fender Right



Rear Fender Right



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026




Rear bumper



Tailgate


Load Body


Rim Front Left


Dash Padding


Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Door Front Right



Door Front Left



Seat Front Left



Door Panel Front Left



Sill Panel Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Air Conditioner



Ball Joint(s) Front Axle Right



Ball Joint(s) Front Axle Left



Belly plates



Belly plates



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026




Gearbox




Engine




Catalytic converter



Tyre Front Right



Tyre Front Left



Rebound Rubber Front Axle Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Rebound Rubber Front Axle Right



Chassis



Differential



Tie Rod End left



Tie Rod End right



Steering Rack Boot Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Steering Rack Boot Right



Radiator Cradle



Engine to silencer pipe



Chassis



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016

DEKRA

CONDITION REPORT

Report No:
2017323661
DATE
10/11/2026



Tyre Rear Right



Tyre Rear Left



Steering Wheel Trim

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFANXXMJ2NJT69016