DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	
Manufacturer	FORD	Registration Number	MB24ZWGP
Model	RANGER 2.2 TDCI XLS 4X4 DSL D-CAB PU AT [2020-2021]	Register Number	
		Date Of First Licensing	
VIN	AFAPXXMJ2PMU70617	Last COR	
Engine Number		License Expiry Date	30/06/2027
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	C - COMMON
Year Model	2021	Fuel	DIESEL
Km Reading	255,305 KM	Transmission	AUTOMATIC
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items


VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Side Mirror Right Damaged	Replace
Front Bumper Cracked	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Chipmarks	Repair
Front Fender Right Residual Traces of Repair	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Load Body Dented	Repair
Windscreen Cracked	Replace
Gearbox Oil Sweat	Repair
BODY EXTERIOR	Minor dents scratches stone chips on some body
BODY EXTERIOR	RESIDUAL TRACES OF POOR REPAIR ON LOAD BODY NOT A
BODY EXTERIOR	Load body has traces of poor repair below standard

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112S	DUNLOP	GRANDTREK	V	2223	1 mm
Front Right	265/65R17	112S	DUNLOP	GRANDTREK	V	2821	3 mm
Rear Left	265/65R17	112S	DUNLOP	GRANDTREK	V	4828	4 mm
Rear Right	265/65R17	112S	DUNLOP	GRANDTREK	V	0000	5 mm
Spare	265/65R17	112T	CONTINENTAL	CROSS CONTAC	V	0000	7 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617

DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	P0069:22-2E	MAP(MANIFOLD ABSOLUTE PRESSURE SENSOR)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617


DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



Brakes report



DIAGNOSTICS



DIAGNOSTICS



DIAGNOSTICS



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617

DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617

DEKRA

CONDITION REPORT


Report No:
2017318093
DATE
27/10/2026




90 DEGREE REAR




90 DEGREE LEFT




LR TYRE TREAD



RR TYRE TREAD



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617

DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



SPAREWHEEL



LICENSE DISC




VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617


DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



Chasis



Oil and dipstick



Water level



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617


DEKRA

CONDITION REPORT


Report No:
2017318093
DATE
27/10/2026




Front Bumper




Front Fender Left



Door Front Left



Door Rear Left



Load Body



Load Body

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617

DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



Load Body



Engine



Gearbox



Side Mirror Right



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617

DEKRA

CONDITION REPORT

Report No:
2017318093
DATE
27/10/2026



Bonnet



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PMU70617