DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	12/11/2026		
Inspection Date	11/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	FZW208L
Model	COROLLA QUEST 1.8 [2020-2022]	Register Number	
VIN	AHTBF8JE101006922	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2027
Color	WHITE	Power / Displacement	
Year Model	2020	Paint Finish	C - COMMON
Km Reading	94,900 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026





Damage	Repair Way
Air cleaner Damaged	Replace
Seat Front Right Excessive Wear & Tear	Repair
Seat Rear Defective	Repair
Door Panel Front Left Damaged	Repair
Bonnet Damaged	Repair
Bonnet slam plate (Shock tower/ Inner tray) Dented	Replace
Front Fender Left Damaged	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Tyre Front Left Smooth	Replace
Tyre Front Right Worn	Replace
Chassis Scratched	Repair
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
CV Joint(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Repair
Radiator Cross Member Welded	Repair
SPAREWHEEL MISSING	REPLACE
BODY EXTERIOR	RESIDUAL TRACES OF POOR REPAIR ON SOME BODY PANELS
INTAKE MANIFOLD DAMAGED	REPLACE
WARNING LIGHT	ILLUMINATED

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.3	3.8	-	
Rear	1.9	2.1	-	
Emergency / Parking	0.6	0.6	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65R15	91V	SAVA	INTENSA	V	4920	2 mm
Front Right	195/65R15	91H	NANKANG	TOUR SPORT	V	0909	1 mm
Rear Left	195/65R15	91V	SAVA	INTENSA	V	1121	2 mm
Rear Right	195/65R15	91V	SAVA	INTENSA HP2	V	1121	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/VSC/TRC	C1201	ENGINE/EV CONTROL SYSTEM MALFUNCTION	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Residual traces of poor repair on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026



INTERIOR (FRONT DRIVER DOOR)



Warning lights



ODOMETER



Manual



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026



90 DEGREE LEFT




REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026




ENGINE 2



CHASSIS




Chasis



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT


Report No:
2017324453
DATE
11/11/2026




RF TYRE TREAD




Sparewheel



Brake report



Diagnostics



Diagnostics



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026



VIN PLATE OR STICKER



DASHBOARD (W/ ENGINE RUNNING)



Water level



Radiator Cradle



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026



Bonnet slam plate (Shock tower/ Inner tray)



CV Joint(s) Front Left (inner/outer)



Gearbox



Gearbox



CV Joint(s) Front Left (inner/outer)



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922


DEKRA

CONDITION REPORT


Report No:
2017324453
DATE
11/11/2026



Belly plates




Tyre Front Right



Tyre Front Left



Front Fender Right



Front Fender Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922


DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026



Rear Fender Left




Rear Fender Right



Rear bumper



Rear bumper



Rear bumper



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026




Door Front Right



Door Front Left



Door Rear Left



Radiator Cross Member



Air cleaner



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT


Report No:
2017324453
DATE
11/11/2026



Boot Lid / Hatch door




Roof



Seat Front Right



Windscreen



Windscreen



Door Panel Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922

DEKRA

CONDITION REPORT

Report No:
2017324453
DATE
11/11/2026



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTBF8JE101006922