DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	16/11/2026		
Inspection Date	16/11/2026		

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	HSL209MP
Model	FORTUNER 3.0 D-4D RB DSL AT [2014-2016]	Register Number	
VIN	AHTZZ69G805042969	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	WHITE	Power / Displacement	
Year Model	2015	Paint Finish	TWO COAT METALLIC
Km Reading	332,657 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT

Report No: 2017325955
DATE 16/11/2026



Damage	Repair Way
Engine Oil Leak	Repair
Center Console / Cubbyhole + Lid Damaged	Replace
Engine Management Lights Set	Repair
Tail Light Left Damaged	Replace
Seat Front Left Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Replace
Rear bumper Damaged	Repair
Roof Damaged	Replace
Windscreen Damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.68	2.26	-	
Rear	3.83	3.41	-	
Emergency / Parking	1.9	1.09	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112T	Goodyear	Wrangler	V	0415	3 mm
Front Right	265/65R17	110T	Lanvigator	Radial	V	4924	1 mm
Rear Left	265/65R17	110T	Lanvigator	Radial	V	4924	2 mm
Rear Right	265/65R17	110T	Lanvigator	Radial	V	4924	1 mm
Spare	265/65R17	110T	Lanvigator	Radial	V	////	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	SRS AIRBAG	B1821	SIDE SQUIB (DRIVE SIDE) CIRCUIT OPEN	HISTROY

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026



90 DEGREE LEFT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick.



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969


DEKRA

CONDITION REPORT


Report No:
2017325955
DATE
16/11/2026




Undercarriage front.




Undercarriage rear.




RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969


DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026




Undercarriage front.



Undercarriage rear.



LICENSE DISC



VIN PLATE OR STICKER



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026



Front Bumper



Bonnet



Front Fender Left



Rear Fender Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969


DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026



Rear bumper



Rear bumper




Boot Lid / Hatch door



Door Rear Right



Door Front Right



Front Fender Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT


Report No:
2017325955
DATE
16/11/2026



Rear Fender Right



Windscreen



Roof



Engine Management Lights



Center Console / Cubbyhole + Lid



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969

DEKRA

CONDITION REPORT

Report No:
2017325955
DATE
16/11/2026



Tail Light Left



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTZZ69G805042969