DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	03/11/2026		
Inspection Date	03/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	NISSAN	Registration Number	KTG644NW
Model	X-TRAIL 2.0 VISIA 7-S [2017-2021]	Register Number	
VIN	JN1JAAT32Z0100425	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2025
Color	SILVER	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT METALLIC
Km Reading	76,852 KM	Fuel	PETROL
Cab / Body Type	SUV	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026



Damage	Repair Way
Engine Management Lights Set	Repair
Windscreen Wiper Damaged	Replace
Seat Front Right Damaged	Repair
Door Panel Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Control Arm Bush(es) Front Axle Left Worn	Replace
Control Arm Bush(es) Front Axle Right Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Spare Tyre Worn	Replace
Front tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.15	3.35	-	
Rear	3.17	3.17	-	
Emergency / Parking	2.31	2.23	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	T155/90D17	101W	Dunlop	Temporary	V	5121	1 mm
Front Right	225/65R17	102H	Goodyear	Assurance	V	1222	0 mm
Rear Left	225/65R17	102H	Goodyear	Assurance	V	1222	0 mm
Rear Right	225/65R17	102H	Yokohama	Radial	V	0622	2 mm
Spare	225/65R17	102H	Goodyear	assurance	V	1222	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS	C1143	STEERING ANGLE SENSOR CIRCUIT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 25 DTC'S AT TIME OF TESTING SEE DTC REPORT.Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Signs of impact damage to rear of vehicle. Repair work done to vehicle below standard. Vehicle body in poor condition. hatch door does not open.
Tyres and Rims: spare wheel deflated. front wheel sizes do not match.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425


DEKRA

CONDITION REPORT


Report No:
2017320969
DATE
03/11/2026




Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026



Water level




Front Bumper




Front Bumper



Bonnet



Front Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT


Report No:
2017320969
DATE
03/11/2026



Door Front Left



Door Rear Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026



Rear Fender Right



Front Fender Right



Door Front Right



Door Rear Right



Seat Front Right



Door Panel Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026




Spare Tyre




Engine Management Lights




Windscreen Wiper



Tyre Rear Left



Tyre Front Right



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425

DEKRA

CONDITION REPORT

Report No:
2017320969
DATE
03/11/2026



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JN1JAAT32Z0100425