DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park - GT**
Requested Date	**12/11/2024**		
Inspection Date	**12/11/2024**		

Vehicle Data

Vehicle Type	**LIGHT LOAD VEHICLE**	Registered Owner	
Manufacturer	**HYUNDAI**	Registration Number	**JL36SSGP**
Model	**BAKKIE 2.6 DECK DSL SKD PU [2015-2020]**	Register Number	
VIN	**KMFZBX7BLKU706637**	Date Of First Licensing	
Engine Number		Last COR	
Doors	**2**	License Expiry Date	**31/03/2024**
Color	**WHITE**	Power / Displacement	
Year Model	**2020**	Paint Finish	**TWO COAT UNI**
Km Reading	**135,428 KM**	Fuel	**DIESEL**
Cab / Body Type	**SINGLE CAB**	Transmission	**MANUAL**

Vehicle Options & Accessories

Items

VEHICLE INSPECTION




Damage	Repair Way
Hoses Defective	Replace
Expansion Bottle Missing	Replace
Battery box Defective	Repair
Air cleaner Damaged	Replace
Wiper Switch Damaged	Replace
Head Light Switch Damaged	Replace
Ashtray Missing	Replace
Heater control Missing	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Windscreen Wiper Damaged	Replace
Number Plate Light Left Defective	Replace
Number Plate Light Right Defective	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Defective	Repair
Seat Front Right Damaged	Repair
Door Panel Front Left Damaged	Repair
Door Panel Front Right Damaged	Repair
Door Hinges Front Right Damaged	Replace
Door Sealing Rubber Front Right Torn / Cut	Replace
Dash Padding Defective	Repair
Window Winder front left Defective	Replace
Window Winder front right Defective	Replace
Steering Wheel Trim Defective	Repair
Side Mirror Right Residual Traces of Repair	Replace
Front Bumper Residual Traces of Repair	Replace
Bonnet Residual Traces of Repair	Replace
Firewall Damaged	Repair
A • Pillar Right Damaged	Repair

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

Damage	Repair Way
C • Pillar Left Dented	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Doorstopper Front Right Defective	Replace
Tailgate Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Damaged	Repair
Roof Damaged	Repair
Load Body Damaged	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle left Defective	Replace
Steering Rack Boot Left Leak	Replace
Control Arm(s) Front Axle Left Defective	Replace
Control Arm(s) Front Axle Right Damaged	Repair
Rim Front Left Dented	Repair
Rim Rear Left Dented	Repair
Rim Rear Right Scratched	Repair
Sub Frame Dented	Repair
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Cab Mounting Point Front Right Defective	Replace
Steering Noisy	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Interior	Gear lever plastic cover missing.
Interior	Steering shaft cover damaged
Road test	Gear selection faulty.
Body and Exterior	Signs of impact damage to front of vehicle.
Body and Exterior	Poor residual traces of repair on some body panels
Body and Exterior	Stone chips and spray work on some body panels
Body and Exterior	Some body panels misaligned
Electrical instruments and components	Idle adjustment switch damaged
Electrical instruments and components	Left and right door open sensors malfunctioning
Warning light illuminated on dashboard	Repair
Tyres and rims	Spare wheel missing

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.17	3.49	-	
Rear	2.3	1.73	-	
Emergency / Parking	1.66	2.22	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70 R15C	104R	Aeolus	Trans Ace	V	1716	1 mm
Front Right	195/70 R15C	104R	Duran	C212	V	1518	2 mm
Rear Left	195/70 R15C	104T	Roadstone	Roadian	V	3615	5 mm
Rear Right	195/70 R15	104T	Roadstone	Rodian	V	1315	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

Diagnostic

A vehicle diagnostic has not been conducted.
Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891
VIN: KMFZBX7BLKU706637
DATE
3 / 19
12/11/2024



Diagnostic report


FRONT RIGHT CORNER


REAR LEFT CORNER


INTERIOR (FRONT DRIVER DOOR)


DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024
VIN: KMFZBX7BLKU706637



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Front chassis



Rear chassis



Idle adjustment switch



Steering shaft cover



Oil cap and dipstick



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Door Hinges Front Right



Door Panel Front Right



C • Pillar Right



Sill Panel Right



Door Sealing Rubber Front Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Rear Fender Right



Bonnet



Front Bumper



Front Bumper



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Windscreen Wiper



Dash Padding



Steering Wheel Trim



Heater control



Center Console / Cubbyhole + Lid



Doorstopper Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



A • Pillar Right



Window Winder front right

VIN: KMFZBX7BLKU706637



Window Winder front left



Side Mirror Right



Wiper Switch



Head Light Switch

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

VIN: KMFZBX7BLKU706637

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Roof



Firewall

VIN: KMFZBX7BLKU706637



Door Front Left



Front Fender Left



C • Pillar Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Dash Padding



Seat Front Left



Door Panel Front Left



Windscreen



Rim Rear Right



Battery box

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Rim Rear Left



Rim Front Left



Brake disc 1. Axle left



Belly plates



Steering Rack Boot Left



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024


Hoses


Hoses


Hoses


Air cleaner


Air cleaner


Cab Mounting Point Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Sub Frame



Control Arm(s) Front Axle Right



Control Arm(s) Front Axle Left



Firewall



Gearbox



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Expansion Bottle



Water level



Tailgate



Rear bumper



Load Body



Number Plate Light Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024



Number Plate Light Right



Ashtray



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016608891

DATE
12/11/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za