DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park -**
Requested Date	**16/04/2026**		
Inspection Date	**16/04/2026**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC**
Manufacturer	**RENAULT**	Registration Number	**KP77KMGP**
Model	**KWID**	Register Number	
VIN	**MEEBBA00200809394**	Date Of First Licensing	
Engine Number		Last COR	
Doors	**5**	License Expiry Date	
Color	**GREEN**	Power / Displacement	
Year Model		Paint Finish	**M - METALLIC**
Km Reading	**138,208 KM**	Fuel	**PETROL**
Cab / Body Type	**HATCHBACK**	Transmission	**MANUAL**

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



Damage	Repair Way
Headlight Left Damaged	Repair
Seat Front Right Damaged	Repair
Carpet Front Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Windscreen Cracked	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Defective	Repair
Sludge on oil cap	Repair
Battery loose	Repair
Vehicle struggle to start	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.1	2.4	-	
Rear	1.3	1.3	-	
Emergency / Parking	1.2	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81T	Ceat	Fuel smart	V	1022	2 mm
Front Right	165/70R14	81T	Ceat	Feul smart	V	0922	3 mm
Rear Left	165/70R14	81T	Ceat	Fuel smart	V	1022	2 mm
Rear Right	165/70R14	81T	Road king	Argos	V	4324	3 mm
Spare	165/70R14	81T	Ceat	Fuel smart	V	1022	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MEMORY	DTC011517	WATER TEMPERATURE SENSOR CIRCUIT VOLTAGE TOO HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



RF TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



LF TYRE TREAD



LR TYRE TREAD



Spare tire no rim



Oil cap and dipstick



Battery loose



Coolant bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



ENGINE 1



CHASSIS



ENGINE 2



VIN PLATE OR STICKER



LICENSE DISC



DIAGNOSTIC REPORT PAGE 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT


Report No:
2017220472
DATE
16/04/2026




DIAGNOSTIC REPORT PAGE 2



DIAGNOSTIC REPORT PAGE 3



DIAGNOSTIC REPORT PAGE 4



SHOCK AND BRAKE REPORT



Seat Front Right



Carpet Front

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



Windscreen



Water level



Bonnet



Front Fender Left



Door Rear Left



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394

DEKRA

CONDITION REPORT

Report No:
2017220472
DATE
16/04/2026



Door Rear Right



Door Front Right



Boot Lid / Hatch door



CV Joint(s) Boot(s) Front Right (inner/outer)



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00200809394