DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	19/08/2026		
Inspection Date	19/08/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	N/A
Model	TRIBER	Register Number	
VIN	MEERBC00500142623	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	152,304 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Damaged	Repair
Fan Belt Damaged	Replace
Engine Management Lights Set	Repair
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Fuse box and fuses Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Door Handle Front Right Damaged	Replace
Door Hinges Front Left Damaged	Replace
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Brake disc 1. Axle left Worn	Repair
Brake disc 1. Axle right Damaged	Replace
Shock Absorber Rear Left Worn	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Spare Tyre Worn	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Engine to silencer pipe Damaged	Replace
Catalytic converter Damaged	Replace
Gearbox Oil Leak	Replace
Battery missing	Replace
Foreign substance on oil filler cap.	Repair
Exhaust system damaged	Replace
Vehicle has a exhaust leak close to the catalytic	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.07	2.02	-	
Rear	1.86	2.12	-	
Emergency / Parking	1.42	1.43	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	85T	Davanti	Radial	V	0824	0 mm
Front Right	165/70R14	81T	Annaite	Radial	V	3525	0 mm
Rear Left	165/80R14	85T	Apollo	Radial	V	3021	2 mm
Rear Right	175/65R14	82T	Falken	Radial	V	4720	1 mm
Spare	175/65R14	82T	Sava	Radial	V	4921	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC001011	INTAKE CAMSHAFT SHIFTER CIRCUIT OPEN CIRCUIT	

Inspection Conditions

No Test Drive
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: SIGNS OF REPAIR WORK DONE TO BODY PANELS. POOR ALIGNMENT TO SOME BODY PANELS. REPAIR WORK DONE TO VEHICLE BELOW STANDARD. VEHICLE BODY IN POOR CONDITION. ACCORDING TO THE AGE AND MILAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS.

Options & Accessories

.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026




Manual.




Oil cap and dipstick.



Oil cap and dipstick.



Diagnostic.



Diagnostic.



Undercarriage front.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623


DEKRA

CONDITION REPORT


Report No:
2017286405
DATE
19/08/2026




Undercarriage rear.



Brake test.




Diagnostic.



Diagnostic.



Diagnostic.



Diagnostic.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT


Report No:
2017286405
DATE
19/08/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623


DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Engine Management Lights



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



Engine Wiring



Fan Belt



Headlight Right



Front Bumper



Front Bumper



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



Front Fender Left



Rear Fender Left




Door Rear Left



Door Front Left



Rear bumper



Rear bumper


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT


Report No:
2017286405
DATE
19/08/2026



Boot Lid / Hatch door




Door Rear Right




Door Front Right



Front Fender Right



Rear Fender Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



Side Mirror Right



Door Handle Front Right




Door Hinges Front Left



Tail Light Right



Tail Light Left



Shock Absorber Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



Engine



Gearbox




Fan Belt



Brake disc 1. Axle left



Brake disc 1. Axle right



Tyre Front Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT


Report No:
2017286405
DATE
19/08/2026



Tyre Front Right



Engine to silencer pipe




Catalytic converter



Bolt(s) / Nut(s) Front Wheel Right



Spare Tyre



Fuse box and fuses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623

DEKRA

CONDITION REPORT

Report No:
2017286405
DATE
19/08/2026



Seat Front Right



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEERBC00500142623