DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	10/11/2026		
Inspection Date	10/11/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	RENAULT	Registration Number	JX46LXGP
Model	SANDERO STEPWAY	Register Number	
VIN	VF15SRAAC64873604	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	BROWN	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	223,893 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No: 2017323761
DATE 10/11/2026



Damage	Repair Way
Tail Light Left Cracked	Replace
Tail Light Right Cracked	Repair
Side Mirror Left Damaged	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Dented	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Tyre Front Left Torn / Cut	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
Front tyre size differs	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.5	2.4	-	
Rear	1.5	1.7	-	
Emergency / Parking	0.8	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	92H	Dunlop	Sp sport	V	4717	3 mm
Front Right	205/55R16	91V	Continental	Contact	V	1123	3 mm
Rear Left	205/55R16	91H	Continental	Contact	V	4519	3 mm
Rear Right	205/55R16	91V	Continental	Contact	V	1123	3 mm
Spare	205/55R16	91V	Continental	Contact	V	////	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	MEMORY	DTC903616	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026



90 DEGREE LEFT




REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap and dipstick



Expention bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026



ENGINE 1



ENGINE 2



CHASSIS



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT


Report No:
2017323761
DATE
10/11/2026




RF TYRE TREAD




Spare wheel




Shock and brake report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604


DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026




LICENSE DISC



VIN PLATE OR STICKER


Bonnet


Water level


Side Mirror Left


Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604


DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026



Side Mirror Left



Door Front Left


Door Rear Left


Rear Fender Left


Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604

DEKRA

CONDITION REPORT

Report No:
2017323761
DATE
10/11/2026



Rear bumper




Boot Lid / Hatch door




Tail Light Left



Tail Light Right



Tyre Front Left



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15SRAAC64873604