DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	**MFC Auction House**	Inspection Location	**MFC** **M57 Pretoria Road - 1619** **Kempton Park -**
Requested Date	**23/04/2026**		
Inspection Date	**23/04/2026**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**MFC**
Manufacturer	**BMW**	Registration Number	**KJ34LKGP**
Model	**320I STEPTRONIC 5F32 [2019-2022]**	Register Number	
VIN	**WBA5F32070FL70102**	Date Of First Licensing	
Engine Number		Last COR	
Doors	**4**	License Expiry Date	**31/05/2026**
Color	**BLUE**	Power / Displacement	
Year Model	**2021**	Paint Finish	**TWO COAT METALLIC**
Km Reading	**211,597 KM**	Fuel	**PETROL**
Cab / Body Type	**SEDAN**	Transmission	**AUTOMATIC**

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



Damage	Repair Way
Side Mirror Right Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Rear bumper Damaged	Repair
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.39	3.59	-	
Rear	2.88	3.01	-	
Emergency / Parking	2.87	3.03	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R19	93Y	Goodyear	Eagle	V	4224	0 mm
Front Right	225/40R19	89Y	Bridgestone	Radial	V	2923	0 mm
Rear Left	255/35R19	92Y	Bridgestone	Radial	V	1623	0 mm
Rear Right	255/35R19	96Y	Bridgestone	Radial	V	4024	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	DME	150302	IGNITION CYLINDER 3 COMBULSION PERIOD TO SHORT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. 21 DTC'S AT TIME OF TESTING SEE DTC REPORT. NO SHOCK TEST PERFORMED.Body • Exterior: Minor dents and scratches and stone chips to some body panels. Signs of repair work done to somebody panels. Poor alignment to somebody panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



Brake test.



Diagnostic.



Diagnostic.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic.



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



90 DEGREE REAR


90 DEGREE LEFT


LF TYRE TREAD


LR TYRE TREAD


RR TYRE TREAD


RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



LICENSE DISC



VIN PLATE OR STICKER


ENGINE 1


Undercarriage front.


Undercarriage rear.


Oil cap.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



Water level



Front Bumper



Front Bumper



Bonnet



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026


Door Rear Left


Rear bumper


Door Rear Right


Door Front Right


Front Fender Right


Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102

DEKRA

CONDITION REPORT

Report No:
2017224744
DATE
23/04/2026



Side Mirror Right



Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBA5F32070FL70102