DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	20/08/2025		
Inspection Date	19/08/2025		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MERCEDES-BENZ	Registration Number	DRJ896L
Model	C200 BLUEEFFICIENCY [2011-2014]	Register Number	
VIN	WDD2040482R200488	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/01/2026
Color	WHITE	Power / Displacement	
Year Model	2011	Paint Finish	C - COMMON
Km Reading	297,450 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No: 2016984715
DATE 19/08/2025



Damage	Repair Way
Engine Oil Leak	Repair
Oil level Insufficient	Repair
Seat Rear Torn / Cut	Repair
Door Handle Front Right Malfunction	Repair
Front Bumper Paintwork • Scratched	Repair
Grill Damaged	Replace
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Sill Panel Right Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Control Arm Bush(es) Front Axle Left Damaged	Replace
Control Arm Bush(es) Front Axle Right Damaged	Replace
Spare Tyre Damaged	Replace
Gearbox Oil Leak	Repair
Engine light on	Repair
Rear tires deferred name brand	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.7	3.1	-	
Rear	2.7	3.5	-	
Emergency / Parking	1.4	1.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45R17	94W	Hilo	Green plus	V	0124	3 mm
Front Right	225/45R17	94W	Hilo	Green plus	V	0124	3 mm
Rear Left	225/45R17	94W	Velocity	Tracmax	V	0624	4 mm
Rear Right	225/45R17	94Y	Sumitomo	Htr z5	V	4923	3 mm
Spare	225/45R17	94W	Voyager	Hp	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	STORED	A10D00	THE POWER SUPPLY IS TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT


Report No:
2016984715
DATE
19/08/2025




Shock and brake report



Diagnostic report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



90 DEGREE FRONT



90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



ENGINE 2



CHASSIS



Expention bottle



Oil cap and dipstick



Water level



Oil level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



Grill



Grill



Bonnet



Windscreen



Spare Tyre



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



Door Rear Right



Door Front Right




Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488


DEKRA

CONDITION REPORT


Report No:
2016984715
DATE
19/08/2025




Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Sill Panel Left



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



Engine



Engine



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Gearbox



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488

DEKRA

CONDITION REPORT

Report No:
2016984715
DATE
19/08/2025



Door Handle Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040482R200488