



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240708082528
Test Time: 2024-07-08 08:25:28
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: AAVZZZ6RZAU066193
Odometer Reading: 210079
License Plate: ZLH924GP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V20.50
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	1
03 - Brakes 1	2
08 - Air Conditioning	0
09 - Electronic central electric	7
15 - Airbag	1
17 - Instrument cluster	0
19 - Gateway	0
25 - Anti-Theft Immobilizer	1
44 - Power Steering	1
56 - Radio	3

DTC (16)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
16684:000	Random/Multiple Cylinder Misfire Detected	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
01201:000	ABS pump voltage supply	Active/static
01200:000	ABS valves voltage supply	Active/static

09 - Electronic central electric (7 DTCs)



DTC	Description	Status
03431:006	Activation of left parking light - Short circuit to B+	Passive/Sporadic
03431:011	Activation of left parking light - Open circuit	Passive/Sporadic
00329:011	Activation for unlocking rear lid - Open circuit	Active/static
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Active/static
01134:004	Alarm horn - No signal/communication	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B10001B	Driver airbag igniter Resistance too high	Active/static

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
01288:007	Terminal 30 steering assistance - Signal too low	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
01305:004	Databus Infotainment - No signal/communication	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00871:011	Right front bass speaker - Open circuit	Active/static

Technician Notes

2016445842

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.