

Shop: --Tel: --Email: --Address: -- Report ID: MAXIA20240328143640 Test Time: 2024-03-28 14:36:40

Technician: Andrick

Page 1

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hilux/--VIN: AHTJB8DD104755373

Customer Information

N MESS I N II

Name: MFC Dekra Nedbank Auction House

Device information

Scanner: MaxiSys MS906 BT

Version: V9.21

Odometer Reading: 153082km License Plate: JNS321MP

Tel: 0861033572

Serial Number: VB8GJCC01509

Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine and ECT	Q 2
ABS/VSC/TRC	Q 9
SRS airbag	© 5
Combination meter	Q 1
Cruise control	ADAS 0 1
4WD	Q 2
Immobilizer	② 0

▲ DTC (20)

Engine and ECT (2 DTCs)

DTC	Description	Status
P0500	Vehicle speed sensor (VSS)	Current
P0500	Vehicle speed sensor (VSS)	History

ABS/VSC/TRC (9 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History
C1405	Right front speed sensor circuit open or short	History
C1406	Left front speed sensor circuit open or short	History
C1407	Right rear speed sensor circuit open or short	Current
C1408	Left rear speed sensor circuit open or short	Current



MaxiSys MS906 BT

Toyota/ Hilux/	Test Time: 2024-03-28 14:36:40	Report ID: MAXIA20240328143640
C1407	Right rear speed sensor circuit open or short	History
C1408	Left rear speed sensor circuit open or short	History
U0126	Lost communication with steering angle sensor (SAS) module	History
SRS airbag (5	DTCs)	
DTC	Description	Status
B1900	Right pretensioner squib circuit short	Current
B1801	Driving side squib circuit open	History
B1900	Right pretensioner squib circuit short	History
B1901	Pretensionersquib (right) circuit open	History
B1906	Pretensioner squib (left) circuit open	History
Combination r	meter (1 DTC)	
DTC	Description	Status
B1507	Turn signal circuit open	Current
Cruise control	(1 DTC)	
DTC	Description	Status
P0500	Vehicle speed sensor (VSS) circuit	Current
4WD (2 DTCs)	
DTC	Description	Status
U0122	Lost communication with vehicle dynamic control (VDC) module	History
U0416	Invalid data received from vehicle dynamic control (VDC) module	History
Technician N 2016322467	otes	
	Customer name:	

Note:Please save a copy of this report for your records.

Page 2

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

Technician: _____

Date: __