

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/ix35(EL)/--
VIN: KMHJU81BLCU560343

Odometer Reading: 256260
License Plate: FWX543MP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(8)

System	Status/DTC
ENG (Engine)	 0
ESP (Electronic Stability Program)	 2
AB (Airbag)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 1
BCM (Body Control)	 0
SJB (Smart Junction Block)	 0

DTC (3)

ESP (Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1208	Left rear wheel speed sensor (WSS) invalid/No signal	History
C1211	Right rear vehicle speed sensor (VSS) invalid/No signal	History

A/C (Air Conditioner) (1 DTC)

DTC	Description	Status
B1688	A/C ionizer fault	Active

Technician Notes

2016903489

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.