



Shop: Dekra MFC
Tel: 0861033572
Email: --
Address: MFC Auction House
M57 Pretoria Road
Glen Marais
Kempton Park
1619

Report ID: MAXIA20231201143858
Test Time: 2023-12-01 14:38:58
Technician: Werner

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/Vitara Brezza/--
VIN: MA3NYFJ1S00726057

Odometer Reading: 46303
License Plate: KLY712NW

Customer Information

Name: MFC MFC

Tel: 0000

Device information

Scanner: MaxiSys MS906 BT
Version: V4.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(10)

System	Status/DTC
Engine/powertrain	 0
TCM	 0
ABS/ESP	 0
Airbag	 0
Instrument Panel Cluster (IPC)/meter/M&A	 0
Power steering	 0
AC	 1
BCM	 1
Immobilizer and/or keyless system	 2
Central gateway control module	 0

DTC (4)

AC (1 DTC)

DTC	Description	Status
B1504	Solar sensor and/or its circuit fault	History

BCM (1 DTC)

DTC	Description	Status
U0231	Lost communication with rain sensing module	Current

Immobilizer and/or keyless system (2 DTCs)

DTC	Description	Status
-----	-------------	--------



B1134 Remote controller battery low

Current

B115B Steering lock unit circuit

History

Technician Notes

2016186904

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.