



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250828122232
Test Time: 2025-08-28 12:22:32
Technician: Sbu

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/CRETA(SU2i)/ALCAZAR(PS7i)/--
VIN: MALPB812LMM074060

Odometer Reading: 186246KM
License Plate: NO reg number

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.90

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned (14)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 2
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 0
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0
RVM (Rear View Monitor)	  0

DTC (3)

AB (Airbag) (1 DTC)



DTC	Description	Status
B1102:00	Battery voltage low	History

IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) (2 DTCs)

DTC	Description	Status
C1313:00	Right front sensor radio frequency channel failure	Active
C1662:00	Auto learning failure	Active

Technician Notes

2016994558

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.