

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/Swift/--
VIN: MBHCZC63S00941401

Odometer Reading: 8034
License Plate: HFP348L

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V4.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(8)

System	Status/DTC
Engine/powertrain	 0
ABS/ESP	 3
Airbag	 0
Instrument Panel Cluster (IPC)/meter/M&A	 1
Central gateway control module	 0
Power steering	 0
BCM	 0
Immobilizer and/or keyless system	 0

DTC (4)

ABS/ESP (3 DTCs)

DTC	Description	Status
C1037	Steering angle sensor power supply voltage	History
C1091	CAN invalid data from ECM	History
C1057	Power supply voltage	History

Instrument Panel Cluster (IPC)/meter/M&A (1 DTC)

DTC	Description	Status
B1840	Vehicle speed data invalid	History

Technician Notes

2016996304

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.