

# Toyota VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Toyota/Avanza/Veloz/--  
 VIN: MHKM5EA1N0K003443

Odometer Reading: 215617  
 License Plate: JW58KRGP

## Customer Information

Name: MFC Dekra Nedbank Auction House








Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
 Version: V9.21

Serial Number: VB8GJCC01509  
 Repair Order Number: --

## System Scanned( 8 )

System	Status/DTC
EFI	 0
ABS	 2
A/B	 0
Combination meter	 4
Body	 0
Electric power steering (EPS)	 1
Combination switch	 0
IMB	 1

## DTC ( 8 )

### ABS ( 2 DTCs )

DTC	Description	Status
C1241	Voltage dropped/over	Current
U0100	Communication with electronic fuel injection (EFI) abnormal	Current

### Combination meter ( 4 DTCs )

DTC	Description	Status
U0100	Communication with electronic fuel injection (EFI)	History
U0129	Communication with ABS/VSC	History
U0131	Communication with electric power steering (EPS)	History
U0151	Communication with A/B ECU	History

### Electric power steering (EPS) ( 1 DTC )

DTC	Description	Status
C1552	PIG voltage abnormality	History

**IMB ( 1 DTC )**

DTC	Description	Status
B2789	Communication faulty (no reply)	Current

**Technician Notes**

2016283934

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.