AUTEL

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240109112003 Test Time: 2024-01-09 11:20:03

Technician: Sbu

Page 1

## Renault VEHICLE DIAGNOSTIC REPORT

**Vehicle Information** 

--/Renault/CLIO IV/--VIN: VF15RSV0A61441020

**Customer Information** 

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

**Device information** 

Scanner: MaxiSys MS906 BT

Version: V12.00

Odometer Reading: 82057 License Plate: FRJ108L

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

## 🔁 System Scanned( 12 )

System		Status/DTC
Injection		<b>3</b>
ABS		<b>©</b> 6
Airbag / pretensioners		<b>Q</b> 4
Instrument panel		<b>©</b> 6
UCH		<b>3</b>
Variable PAS		<b>Q</b> 2
UPC		<b>Q</b> 12
Parking prox can	APAS	<b>Q</b> 1
Radio	APAS	<b>3</b>
Air conditioning		<b>Q</b> 1
Multimedia interface		<b>Q</b> 1
Hands-free module		<b>©</b> 5

## ▲ DTC (47)

## Injection (3 DTCs)

DTC	Description	Status
DTC056016	Computer supply voltage Permanent low level	Memory
DTC083362	Clutch switch signal consistency	Memory

AUTEL www.autel.com

MaxiSys MS906 BT

/Renault/CLIO IV	Test Time: 2024-01-09 11:20:03	Report ID: MAXIA20240109112003
/nenault/CLIU IV	1est time: 2024-01-09 11:20:03	перопти. МАХІАZUZ4UTU9TTZUU3
DTC1525F3	Consistent multiplex signals for CC/SL The data supplied to the cruise control or speed limiter are not correct.	Memory
ABS (6 DTCs)		
DTC	Description	Status
DTC406C13	Vacuum sensor circuit Open circuit	Memory
DTC406C96	Vacuum sensor circuit Internal component failure	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCC42200	Invalid UCH multiplex signals	Memory
DTCF00313	Computer power supply Open circuit	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory
Airbag / pretens	sioners ( 4 DTCs )	
DTC	Description	Status
DTC80D223	Warning light circuit fault	Memory
DTC80D224	Warning light circuit fault	Memory
DTC903616	Power supply voltage	Memory
DTC903617	Power supply voltage	Memory
Instrument pan	el ( 6 DTCs )	
DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory
DTC940413	Airbag fault warning light circuit Open circuit	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory
DTC941211	External temperature sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory
UCH (3 DTCs)		
DTC	Description	Status
DTC951924	Neutral switch	Memory

AUTEL www.autel.com MaxiSys MS906 BT Page 2

/Renault/CLIO IV	Test Time: 2024-01-09 11:20:03	Report ID: MAXIA20240109112003
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC956023	Start of clutch switch travel circuit	Memory
Variable PAS ( 2	2 DTCs)	
DTC	Description	Status
DTCF00313	Computer power supply Open circuit	Memory
DTCF00317	Computer power supply Excess voltage	Memory
UPC (12 DTCs)		
DTC	Description	Status
DTC921215	Left-hand dipped headlight circuit Open circuit or short circuit to +12 V	Memory
DTC921315	Right-hand dipped headlight circuit Open circuit or short circuit to +12 V	Memory
DTC921D11	Front wiper protection Short circuit to earth.	Memory
DTC922111	Rain/luminosity sensor circuit Short circuit to earth.	Memory
DTC922181	Rain/luminosity sensor circuit Invalid.	Memory
DTC922211	Steering column lock +APC circuit Short circuit to earth.	Memory
DTC923696	Rain/light sensor Internal fault	Memory
DTC924111	Left-hand daytime running lights circuit Short circuit to earth.	Memory
DTC927094	Combined stalk under steering wheel circuit Performance down or incorrect operation	Memory
DTC928114	Battery voltage 12 V Open circuit or short circuit to earth	Memory
DTC928214	Battery voltage 12 V Open circuit or short circuit to earth	Memory
DTC928314	Battery voltage 12 V Open circuit or short circuit to earth	Memory
Parking prox ca	n(1DTC)	
DTC	Description	Status
DTCA74187	Brake information Missing message	Memory

Radio (3 DTCs)

AUTEL www.autel.com MaxiSys MS906 BT Page 3

/Renault/CLIO IV	Test Time: 2024-01-09 11:20:03	Report ID: MAXIA20240109112003
DTC	Description	Status
DTC932813	Microphone Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory
Air conditioning	(1 DTC)	
DTC	Description	Status
DTCF00316	Computer supply voltage Low voltage	Memory
Multimedia inte	erface (1 DTC)	
DTC	Description	Status
DTC930316	Power supply Low voltage	Memory
Hands-free mo	dule ( 5 DTCs )	
DTC	Description	Status
DTCA0334A	Dongle	Memory
DTCA05111	Steering lock Short circuit to earth.	Memory
DTCA05177	Steering lock Control position inaccessible	Memory
DTCA0571C	Steering column lock protection Component failures	Memory
DTCA06004	Wake up signal Internal fault	Memory
Technician No 2016221837	tes	
	Cuctomer name:	

Customer name: ,	
Technician:	
<b>5</b> .	

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

