

Shop: DEKRA MFC Tel: --Email: --Address: MFC Auction House Kempton Park Report ID: MAXIA20240220092535 Test Time: 2024-02-20 09:25:35 Technician: Sbu

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information	
/Renault/CLIO IV/	Odometer Reading: 123268
VIN: VF15RSV0A61730901	License Plate: JD79RVGP
Customer Information	
Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE	Tel: 0861033572
Device information	
Scanner: MaxiSys MS906 BT	Serial Number: VB8GJCC01482
Version: V12.00	Repair Order Number:

System Scanned(12)

System		Status/DTC
Injection		🔇 10
ABS		🔇 6
Airbag / pretensioners		◀
Instrument panel		🔇 6
UCH		3 2
Variable PAS		3
UPC		Q 11
Parking prox can	ADAS	3 1
Radio	ADAS	Q 4
Air conditioning		3 2
Multimedia interface		Q 1
Hands-free module		Q 6

DTC (56) Injection (10 DTCs)

DTC	Description	Status
DTC013511	Upstream oxygen sensor heating circuit Short circuit to earth.	Memory
DTC013513	Upstream oxygen sensor heating circuit Open circuit	Memory

Report ID: MAXIA20240220092535

DTC056016	Computer supply voltage Permanent low level	Memory
DTC056429	Speed limiter/cruise control function Signal incoherence.	Memory
DTC061A61	Computer Internal electronic fault	Memory
DTC083362	Clutch switch signal consistency	Memory
DTC1525F3	Consistent multiplex signals for CC/SL The data supplied to the cruise control or speed limiter are not correct.	Memory
DTC224412	Proportional richness sensor circuit Short-circuit to +12V	Memory
DTC226321	Boost pressure circuit Turbocharging pressure is too high.	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory
ABS (6 DTCs)		
DTC	Description	Status
DTC403413	Front R/H wheel speed sensor circuit Open circuit	Memory
DTC406C13	Vacuum sensor circuit Open circuit	Memory
DTC406C96	Vacuum sensor circuit Internal component failure	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCC42200	Invalid UCH multiplex signals	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory
Airbag / pretens	sioners (4 DTCs)	
DTC	Description	Status
DTC80D223	Warning light circuit fault	Memory
DTC80D224	Warning light circuit fault	Memory
DTC903616	Power supply voltage	Memory
DTC903617	Power supply voltage	Memory
Instrument pane	el (6 DTCs)	
DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory

/Renault/CLIO IV	Test Time: 2024-02-20 09:25:35	Report ID: MAXIA20240220092535
DTC940413	Airbag fault warning light circuit Open circuit	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory
DTC941211	External temperature sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory
UCH (2 DTCs)		
DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC956401	Brake pedal contact circuit	Memory
Variable PAS (3 DTCs)	
DTC	Description	Status
DTCF00313	Computer power supply Open circuit	Memory
DTCF00316	Computer power supply Low voltage	Memory
DTCF00317	Computer power supply Excess voltage	Memory
UPC (11 DTCs)	
DTC	Description	Status
DTC921D11	Front wiper protection Short circuit to earth.	Memory
DTC922111	Rain/luminosity sensor circuit Short circuit to earth.	Memory
DTC922181	Rain/luminosity sensor circuit Invalid.	Memory
DTC922211	Steering column lock +APC circuit Short circuit to earth.	Memory
DTC924111	Left-hand daytime running lights circuit Short circuit to earth.	Memory
DTC927094	Combined stalk under steering wheel circuit Performance down or incorrect operation	Memory
DTC927096	Combined stalk under steering wheel circuit Internal electronic fault	Memory

/Renault/CLIO IV	Test	Time: 2024-02-20 09:25:35	Report ID: MAXIA20240220092535
DTC927415	Backlights and number plate lig Open circuit or short circuit to -	ghting +12 V	Memory
DTC928114	Battery voltage 12 V Open circuit or short circuit to e	earth	Memory
DTC928214	Battery voltage 12 V Open circuit or short circuit to e	earth	Memory
DTC928314	Battery voltage 12 V Open circuit or short circuit to e	earth	Memory
Parking prox ca	n (1 DTC)		
DTC	Description		Status
DTCA74187	Brake information Missing message		Memory
Radio (4 DTCs)		
DTC	Description		Status
DTC932811	Microphone Short circuit to earth.		Memory
DTC932813	Microphone Open circuit		Memory
DTC934262	Unit locked Computer locked		Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold		Memory
Air conditioning	(2DTCs)		
DTC	Description		Status
DTC910549	Computer Internal electronic fault		Memory
DTCF00316	Computer supply voltage Low voltage		Memory
Multimedia inte	rface (1 DTC)		
DTC	Description		Status
DTC930316	Power supply Low voltage		Memory
Hands-free mo	dule (6 DTCs)		
DTC	Description		Status
DTCA0334A	Dongle		Memory
DTCA05111	Steering lock Short circuit to earth.		Memory
DTCA0571C	Steering column lock protection Component failures	1	Memory

/Renault/CLIO IV	Test Time: 2024-02-20 09:25:35	Report ID: MAXIA20240220092535
DTCA06004	Wake up signal Internal fault	Memory
DTCA07111	Driver's door hands-free button Short circuit to earth.	Memory
DTCA07211	Passenger door hands-free button Short circuit to earth.	Memory

Technician Notes

2016274450

Customer name:

Technician:

Date:

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.